

STATE OF NEW MEXICO  
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.O.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION  
P. O. BOX 2088  
SANTA FE, NEW MEXICO 87501

Form C-103  
Revised 10-1-78

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Free <input type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT TO DRILL" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input type="checkbox"/> OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER		7. Unit Agreement Name
2. Name of Operator Amoco Production Company		8. Farm or Lease Name Turner
3. Address of Operator P. O. Box 68 Hobbs, NM 88240		9. Well No. 3
4. Location of Well UNIT LETTER <u>P</u> <u>560</u> FEET FROM THE <u>South</u> LINE AND <u>760</u> FEET FROM THE <u>East</u> LINE, SECTION <u>29</u> TOWNSHIP <u>21-S</u> RANGE <u>37-E</u> N.M.P.M.		10. Field and Pool, or Wildcat Blinebry/Tubb Oil & Gas
15. Elevation (Show whether DF, RT, GR, etc.) 3477' DF		12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <u>Commingle Tubb and Blinebry</u> <input checked="" type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Propose to downhole commingle the Tubb and Blinebry horizons as follows:

Rig up wireline truck. Open Garret Oil Tool B.C. valve (sliding sleeve type valve) located at apx. 5637' with wireline. Move in swab unit and swab down tubing. Evaluate production. If valve will not open, move in service unit and release tubing from Baker Model C1 receptacle. Pull up 1 joint and swab tubing down. Evaluate and return to production. (Approval to commingle the Blinebry and Tubb horizons was granted by Adrin. Order No. DHC-450).

0 + 5 - NMOCD, H      1 - R. E. Ogden, Hou      1 - F. J. Nash, Hou      1 - CLF

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Cathy L. Forman TITLE Asst. Admin. Analyst DATE 2/20/84

ORIGINAL SIGNED BY JERRY SEXTON  
DISTRICT 1 SUPERVISOR

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE FEB 22 1984

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

FEB 21 1984

O.C.D.  
HOBBS OFFICE

RECEIVED FEB 21 1984  
FEB 21 1984