

NEW MEXICO OIL CONSERVATION COMMISSION

Santa Fe, New Mexico

MISCELLANEOUS NOTICES

Submit this notice in TRIPLICATE to the District Office, Oil Conservation Commission, before the work specified is to begin. A copy will be returned to the sender on which will be given the approval, with any modifications considered advisable, or the rejection by the Commission or agent, of the plan submitted. The plan as approved should be followed, and work should not begin until approval is obtained. See additional instructions in the Rules and Regulations of the Commission.

Indicate Nature of Notice by Checking Below

NOTICE OF INTENTION TO CHANGE PLANS		NOTICE OF INTENTION TO TEMPORARILY ABANDON WELL		NOTICE OF INTENTION TO DRILL DEEPER	
NOTICE OF INTENTION TO PLUG WELL		NOTICE OF INTENTION TO PLUG BACK		NOTICE OF INTENTION TO SET LINER	
NOTICE OF INTENTION TO SQUEEZE		NOTICE OF INTENTION TO ACIDIZE		NOTICE OF INTENTION TO SHOOT (Nitro)	
NOTICE OF INTENTION TO GUN PERFORATE		NOTICE OF INTENTION (OTHER) Dual Complete	X	NOTICE OF INTENTION (OTHER)	

OIL CONSERVATION COMMISSION
SANTA FE, NEW MEXICOHobbs, New Mexico
(Place)June 27, 1960
(Date)

Gentlemen:

Following is a Notice of Intention to do certain work as described below at the Socony Mobil Oil Company, Inc.

(Company or Operator) C. Hardy Well No. 3 in C (Unit)
NE $\frac{1}{4}$ NW $\frac{1}{4}$ of Sec. 29, T. 21S, R. 37E, NMPM, Drinkard Pool
 (40-acre Subdivision)
 County.

FULL DETAILS OF PROPOSED PLAN OF WORK
(FOLLOW INSTRUCTIONS IN THE RULES AND REGULATIONS)

TD: 6650'

Perforations: 6590 - 6645'.

Proposed to plug back and dual complete in the Blinebry (Gas) and Tubb (Gas) Zones. Set cementer at 6260' and cement below with 75 sacks Neat 2000 psi. Perforate Tubb Zone at 6240', 6232, 6207', 6191', 6185', 6177', and 6170' and the Blinebry Zone at 5560', 5658', 5641', and 5623' with 6 shots in horizontal plane at each level. Set BP at 6250' and cementer at 6220' and Frac with 2000 gals water with 15# J-100 and 2" 20/40 Ottowa Sand/gal. Set BP at 6220' and cementer at 6200' and frac with 2000 gals of above fluid. Set BP at 6200' and cementer at 6150' and frac with 4000 gals of above fluid. Set BP at 5680' and cementer at 5650' and Frac with 2000 gals of above fluid. Set BP at 5650' and cementer at 5630' and frac with 2000 gals above fluid. Set BP at 5630' and cementer at 5600' and frac with 2000 gals above fluid. Run retrievable Production packer at 5950' on 2" tubing with 300' of stinger and blankoff tool in Otis Type "J" nipple at 5980' with Otis sliding side door position at 5700'. Swab off Blinebry. Shut sliding side door and pull blankoff tool. Swab off Tubb and complete.

Approved _____
Except as follows:Socony Mobil Oil Company, Inc.
Company or OperatorBy [Signature]
Position District Superintendent
Send Communications regarding well to:Approved _____
OIL CONSERVATION COMMISSION

By _____

Name Socony Mobil Oil Company, Inc.

Title _____

Address Box 2406, Hobbs, New Mexico.

cc: Sunray, Sinclair, Pan American, Gulf, Ohio, Texaco, Getty