

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-06899
5. Indicate Type of Lease STATE ☐ FEE ☒
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name V. Linam
8. Well No. 2
9. Pool name or Wildcat Hare (San Andres)

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL ☐ GAS WELL ☒ OTHER
2. Name of Operator Oryx Energy Company
3. Address of Operator P. O. Box 1861, Midland, Texas 79702
4. Well Location Unit Letter <u>B</u> : <u>660'</u> Feet From The <u>North</u> Line and <u>1980</u> Feet From The <u>East</u> Line Section <u>East 29</u> Township <u>21-S</u> Range <u>37-E</u> NMPM Lea County
10. Elevation (Show whether DF, RKB, RT, GR, etc.)

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPNS. ☐	PLUG AND ABANDONMENT ☐
PULL OR ALTER CASING ☐		CASING TEST AND CEMENT JOB ☐	
OTHER: ☐		OTHER: Unsuccessful Recompletion ☒	

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

4/9/91 MIRU Xpert WS.
4/11/91 Set RBP @ 5550'.
4/12/91 Test RBP to 2500 psi. Dump 3 sx sand. EIR into Grayburg perms 3689'-3808'. Sqz. perms 3689'-3808' with 200 sx Class C w/1.5% CF-1 & 2% CaCl₂. Sqz to 1500 psi. Reverse out 33 sx. & WOC.
4/16/91 RIH w/6-1/8" bit. DOC 3595'-3608'.
4/17/91 Drill hard cmt from 3608'-3858'. Test sqz to 1000 psi.
4/18/91 Ran CBL from 5475' to 2500'.
4/19/91 Perf Glorieta 5104'-14', 5120'-30', 5138'-49', 5154'-63, 5181'-92', 5234'-46'.
2 JHPF Total 124 holes.

(Cont. on Page 2)

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE _____ TITLE Proration Analyst DATE 6-3-91

TYPE OR PRINT NAME Maria L. Perez TELEPHONE NO. (915)688-0375

(This space for State Use)

Orig. Signed by
Paul Kautz
Geologist

APPROVED BY _____ TITLE _____ DATE JUN 06 1991

CONDITIONS OF APPROVAL, IF ANY:

3A Lawrence Skelly AB

7

RECEIVED

JUN 05 1954

1

HONOLULU

12. Describe Proposed or Completed Operations.

4-20-91 Acdz Glorieta perfs w/600 gal 20% HCL.
4-23-91 Swab 12 hrs., rec. 111 BLAW, 86 BW, Trace Oil.
4-24-91 Sqz. perfs 5104-5246 w/200 sxs Class C cmt.
4-25-91 Tag & drill out cmt 5013-5016, CR 5016-5019 & hard cmt 5019-5065. Circ hole clean.
4-26-91 Cont drlg cmt 5065 to 5246. Circ. hole clean. Test sqz to 500 psi - OK.
4-27-91 Set RBP @4201. Test RBP to 1000#, OK, Perf. 8 sqz holes @ 4030'.
4-30-91 Sqz holes at 4030; w/50 sxs Class C.
5/1/91 TIH w/6-1/8" bit. Drill hard cmt to 4030', Circ clean, test sqz to 5000 psi.
5/2/91 Sqz. holes at 4030' w/50 sxs Class C cmt.
5/3/91 Drill hard cmt. to 4010'. Circ. clean. Test sqz to 500 psi, OK.
5/4/91 Perf San Andres 3933-92, 2 JSPF, total 118 holes.
5/7/91 Acidize San Andres perfs 3933-92' w/1500 gal 20% NEFEHCL.
5/8/91 Rec 6 B0.
5/9/91 Sqz. SA perfs 3933-92 w/200 sxs CL'C' cmt.
5/11/91 Drlg. hard cmt to 4004'. Clean out. Test sqz to 500 psi for 5 min. OK.
TIH w/7" Bkr. Mod 'R' DG Pkr on 2-7/8" tbg. Set Pkr @ 3601'.
5/15/91 RIH w/ MA, SN, & 2-3/8" tbg to 6584'. RIH w/1-1/4" pump. Hang well on.
Chevron will finish tie in.

RECEIVED

JUN 0 1961

NOBBE