

Submit 3 Copies
to Approving
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-39

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Aztec, NM 88210

DISTRICT III
1000 Rio Arriba Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.
30-025-06905

5. Indicate Type of Lease

STATE ☐

FEE ☒

6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:

OIL
WELL ☒

GAS
WELL ☐

OTHER

2. Name of Operator

Chevron U.S.A. INC.

3. Address of Operator

P.O. Box 670, Hobbs, NM 88240

4. Well Location

Unit Letter N : 1980 Feet From The West Line and 660 Feet From The South Line

Section 30 Township 21S Range 37E NMPM Lea County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

3510'

7. Lease Name or Unit Agreement Name

H. T. Mattern (NCT-B)

8. Well No.

11

9. Foot name or Wildcat

Penrose Skelly - GB

11.

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

PULL OR ALTER CASING ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐

ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐

PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER: perf, acdz, frac ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Work performed: 6-12-89 thru 6-15-89

TD: 3800 PB: 3794

POH w/production equipment. Cleanout to 3794'. Perf 3705', 3710-20, 3724-32, 3747, 3752 & 3786 w/4" guns, 2-1/2" SPF, 180° phase, total 44 holes. Acidize down tbg w/3000 gallons 15% NEFE HCL. Swab. Frac Penrose Skelly 3705-3786 w/20,000 gallons 40# gelled BW and 35,500 lbs 20/40 ottawa sand, flush to 3630' w/gelled BW. Swab. RIH w/ production tbg to 3768 EOT, SN @ 3731'. Hand on, load w/ CKF, test pump to 500psi, ok. Turn over to production.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

Jerry Sexton

TITLE Technical Assistant

DATE 6-20-89

TYPE OR PRINT NAME

TELEPHONE NO.

(This space for State Use)

ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT I SUPERVISOR

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

JUN 21 1989

RECEIVED

JUN 20 1989

OCD
HOBBS OFFICE