State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103

Submit 3 Copies to Appropriate District Office

Revised 1-1-89

DISTRICT II P.O. Drawer DD, Ariesia, NM 88210 DISTRICT III 1000 Rio Brazos Rd., Aziec, NM 87410 SUNDRY NOTICES AND RI (DO NOT USE THIS FORM FOR PROPOSALS TO D. DIFFERENT RESERVOIR. USE "AI (FORM C-101) FOR SUC! L. Type of Weil: OIL WELL WELL GAS WELL	RILL OR TO DEEPEN OR PLUG BACK TO A PPLICATION FOR PERMIT	WELL API NO. 30-025-06905 5. Indicate Type of Lease STATE 6. State Oil & Gas Lease No. 7. Lease Name or Unit Agreement Name H. T. Mattern (NCT-B)
2. Name of Operator Chevron U.S.A. Inc.		& Weil No.
P.O. Box 670, Hobbs, NM 8824 Well Location Unit Letter N : 1980 Feet From T		9. Pool name or Wilden Penrose Skelly - G B South
20	210	
	21S Range 37E 1 levation (Show weither DF, RKB, RT, GR, etc.)	NMPM Lea County
	3510'	
NOTICE OF INTENTION TO		port, or Other Data SEQUENT REPORT OF:
	DABANDON REMEDIAL WORK	ALTERING CASING
TEMPCRARILY ABANDON CHANGE	PLANS COMMENCE DRILLING	OPNS. PLUG AND ABANDONMENT
PULL OR ALTER CASING	CASING TEST AND CE	MENT JOB
OTHER:	OTHER:	
It is proposed to cleanout to 3796', (PBTD). Perforate (Penrose Skelly) 3705',3710-3720', 3724'-3732', 3747',3752' and 3786', using 4" guns with 2 JHPF, 180° phaseing. Acidize all perforations (3705'-3786') using 3000 gallons 15% NEFE HCL. Swab back, residue. Frac Penrose Skelly (3705'-3786') with 20,000 gallons 8.6# BW and 35,5001bs 20/40 ottawa sand. Close in overnight, swab back. RIH w/production equipment, turn over to production dept.		
I hereby certify that the information above is true and complete to the i	best of my knowledge and helief.	
SIGNATURE S. X. Somas	me Technical Assis	Stant 6-6-89
TYPE OR PRINT NAME	mie Termittat ASSIS	
(This space for State Use) ORIGINAL SIGNED BY JERRY SEXT DISTRICT 1 SUPERVISOR APTROVED BY	TON TITLE	JUN 7 1989
CONTROL OF SERVICE IN THE	Bus average	