Submit 3 Copies To Appropriate District State of New Mexico Form C-103 Office Energy, Minerals and Natural Resources Revised March 25, 1999 District I WELL API NO. 30-025-06909 1625 N. French Dr., Hobbs, NM 87240 District II OIL CONSERVATION DIVISION 811 South First, Artesia, NM 87210 5. Indicate Type of Lease 2040 South Pacheco District III 1000 Rio Brazos Rd., Aztec, NM 87410 Santa Fe, NM 87505 STATE \square FEE K District IV 2040 South Pacheco, Santa Fe, NM 87505 6. State Oil & Gas Lease No. SUNDRY NOTICES AND REPORTS ON WELLS 7. Lease Name or Unit Agreement Name: (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH V.M. Henderson PROPOSALS.) 1. Type of Well: Oil Well 🔯 Gas Well 🗌 Other 2. Name of Operator 8. Well No. Chevron U.S.A. Inc. Address of Operator 9. Pool name or Wildcat 15 Smith Road, Midland Texas Blinebry 4. Well Location Unit Letter H 1980 feet from the north line and 660 feet from the east line 30 Section Township 21-S Range 37-E **NMPM** County Lea 10. Elevation (Show whether DR, RKB, RT, GR, etc.) 11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON ∇ REMEDIAL WORK ALTERING CASING **TEMPORARILY ABANDON CHANGE PLANS** COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT PULL OR ALTER CASING MULTIPLE CASING TEST AND COMPLETION CEMENT JOB OTHER: OTHER: 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation. 1. Notify OCD 24hrr prior to Mi &Ru. 2. Set 5 1/2 CIBP @ 5475, spot 25sx plug 5475-5275(Blinebry) WOC Tag. 3. Displace hole w/MLF, 9.5 # Brine w/25 # Gel P/BBL. 4. Spot 25sx plug 5250-5050 (sqz,d Paddock perfs) 5. Spot 30sx plug 4010-3750 (sqz,d Penrose Skelly perfs) 6. Spot 25sx plug 2925-2600(8 5/8 shoe, B-salt) WOC Tag 7. Perf 4 holes @ 1400, sqz 50sx plug 1400-1200(T-salt) WOC Tag 8. Perf 4 holes @ 310, sqz 75sx plug 310 - surf , 5 1/2 X 8 5/8csqs (13 3/8 shoe, surf) WOC Tag. THE COMMISSION MUST BE NOTIFIED 24 9. Install dry hole marker. HOURS PRIOR TO THE BEGINNING OF PLUGGING OPERATIONS FOR THE C-103 TO BE APPROVED. I hereby certify that the information above is true and complete to the best of my knowledge and belief. TITLE HES Specialist SIGNATURE. Type or print name Telephone No. 915.687.7153

ORIGINAL SIGNED BY

OC FIELD REPRESENTATIVE II/STAFF

GARY MITTEN

NOV 1 4 20**02**

<u>ر</u>

(This space for State use)

Conditions of approval, if any:

APPROVED BY

