

10. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT --" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		7. Unit Agreement Name	
2. Name of Operator TEXACO, Inc.		8. Farm or Lease Name V.M. Henderson	
3. Address of Operator P.O. Box 728 - Hobbs, New Mexico 88240		9. Well No. 5	
4. Location of Well UNIT LETTER B 1980' FEET FROM THE East LINE AND 660' FEET FROM THE North LINE, SECTION 30 TOWNSHIP 21-S RANGE 37-E NMPM.		10. Field and Pool, or Wildcat Penrose-Skelly	
15. Elevation (Show whether DF, RT, GR, etc.) 3996' DF		12. County Lea	

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	
		OTHER Recomplete from Penrose Skelly to Eumont Queen Gas <input checked="" type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Pulled rods and pump from Penrose string. Pulled Penrose tubing.
2. Ran RBP to 4500' in 7" casing and dump sand on top of RBP. Run cement re-tainer to 3651' and squeezed Penrose Skelly perforations 3689'-3874' w/250 sacks Class C cement w/3 lbs. salt and .3% CFR-2 to 2200#.
3. Penrose Skelly zone abandoned. Dually producing from Paddock and Eumont Queen Gas zones.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED  TITLE Asst. Dist. Supt. DATE May 31, 1974

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY: