

NO. OF COPIES REQUIRED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION

P. O. BOX 2088

SANTA FE, NEW MEXICO 87501

For
Ref

3a. Indicate Type of Lease
State ☐

3b. State Oil & Gas Lease

SUNDRY NOTICES AND REPORTS ON WELLS

DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO REWORK OR PLUG BACK IN A DIFFERENT RESERVOIR.
USE APPLICATION FOR PERMIT TO DRILL OR REWORK WELL PROPOSALS.

1. ☒ OIL WELL ☐ GAS WELL ☐ OTHER	7. Unit Agreement Name Central Drinkard
2. Name of Operator Chevron U.S.A. Inc.	8. Term of Lease (year)
3. Address of Operator P. O. Box 670, Hobbs, NM 88240	9. Well ID 136
4. Location of Well UNIT LETTER H 1980 FEET FROM THE North 330 FEET FROM THE East LINE, SECTION 31 TOWNSHIP 21S RANGE 37E	10. Field and Pool, or Wildcat Drinkard
15. Elevation (Show whether DE, RT, GR, etc.) 3470 GL	12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☒	PLUG AND ABANDON ☐	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANE ☐	COMMENCE DRILLING OPER. ☐	PLUG AND ABANDONMENT ☐
PULL OR ALTER CASING ☐	OTHER ☐	CASING TEST AND CEMENT JOBS ☐	

17. Describe Proposals or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

MIRU PU. POH with rods. NDWH NU BOP. Tag bottom and POH with tubing.
PU bit and drill collars. TIH. RU stripper head and power swivel. RU
foam unit establish circulation and clean out open hole to PBTD of 6610'.
Set retrievable 80' 5½" slotted liner @ 6610'. RU production equipment
and return to production.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

Eddie W. Seay

Oil & Gas Inspector

Division Drilling Manager

10-4-1985

OCT 8 - 1985

RECEIVED
OCT - 7 1985
O.C.D.
HOBBS OFFICE