NEW MEXICO OIL CONSERVATION COMMISSION Santa Fe, New Mexico

٠,

MISCELLANEOUS NOTICES

Submit this notice in TRIPLICATE to the District Office, Oil Conservation Commission, before the work specified is to begin. A copy will be returned to the sender on which will be given the approval, with any modifications considered advisable, or the rejection by the Commission or agent, of the plan submitted. The plan as approved should be followed, and work should not begin until approval is obtained. See additional instructions in the Rules and Regulations of the Commission.

	Indicate Nature of Notice by Checking	Below
NOTICE OF INTENTION TO CHANGE PLANS	Notice of Intention to Temporarily Abandon Well	Notice of Intention to Drill Deeper
Notice of Intention to Plug Well	Notice of Intention to Plug Back	Notice of Intention to Set Liner
Notice of Intention to Squeeze	Notice of Intention to Acidize	Notice of Intention to Shoot (Nitro)
Notice of Intention to Gun Perforate	Notice of Intention (Other)	Notice of Intention (Other)
OIL CONSERVATION COMMISSION SANTA FE, NEW MEXICO	Hobbs, New Mexico	January 13, 1956
Gentlemen:		
•		
Gulf Oll Gerporation (Company or Oper	ator) V. T. McGorrank	Well No. 4 in (Unit)
(40-acre Subdivision) 4 of Sec32	T. 21-S , R. 37-8 , NM	PM., Panrose-Skelly Poo
In order to is 1. Pull	tubing.	D REGULATIONS) sed to fracture treat as follows:
In order to in l. Pull 2. Ran a 3. Ran a inter 4. Treat 5. Pull neces	ow instructions in the rules an increase production it is proposed tubing. Iteel line measurement. Clean 1-7/8" tubing with Lynes Self 2 val 3690-3700'. I with 8000 gelled lease oil with 1000 gelled lease oil with 10000 gelled lease oil with 1000 gelled lease oi	D REGULATIONS) sed to fracture treat as follows: out with sand pump if necessary. Anchoring formation packer in
In order to in l. Pull 2. Ran a 3. Ran a inter 4. Treat 5. Pull neces 6. Swab	ow instructions in the rules an arease production it is propose tubing. Iteel line measurement. Clean 2-7/8" tubing with Lynes Self and 3690-3700'. It with 3000 gelled lease oil with 2-7/8" tubing and packer, remissary. and test. By	D REGULATIONS) sed to fracture treat as follows: out with sand pump if necessary. Inchoring formation packer in ith l# sand per gallen.
In order to in l. Pull 2. Ran a 3. Ran a inter 4. Treat 5. Pull neces 6. Swab	ow instructions in the rules an arease production it is propose tubing. Iteel line measurement. Clean 1-7/8" tubing with Lynes Self 1-7/8" tubing with Lynes Self 1-7/8" tubing and packer, remissary. and test. By	D REGULATIONS) sed to fracture treat as follows: out with sand pump if necessary. Inchoring formation packer in Ith 1# sand per gallon. In 2-3/8" tubing and packer if Company or Operator Company or Operator Supt. of Front.