

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

DISTRICT I

P.O. Box 1980, Hobbs, NM 88240

DISTRICT II

P.O. Drawer 0d, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, Nm 87410

API NO. (assigned by OCD on New Wells)

30-025-06934

5. Indicate Type of Lease

STATE

☒

FEE

☒

6. State Oil & Gas Lease No.

N/A

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

7. Lease Name or Unit Agreement Name

W.T. MC COMACK

1. Type of Well:

OIL

GAS

WELL

☒

WELL

☐

OTHER

2. Name of Operator

CHEVRON U.S.A. INC.

8. Well No.

5

3. Address of Operator

P.O. BOX 1150 MIDLAND, TX 79702 ATTN: NITA RICE

9. Pool name or Wildcat

PENROSE-SKELLY - GB

4. Well Location

Unit Letter

G

1980

Feet From The NORTH

Line and

1980

Feet From The

EAST

Line

Section

32

Township

21S

Range

37E

NMPM

LEA

County

10. Elevation(Show whether DF, RKB, RT, GR, etc.)

3456 GE

11

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK

☐

PLUG AND ABANDON

☐

TEMPORARILY ABANDON

☐

CHANGE PLANS

☐

PULL OR ALTER CASING

☐

OTHER:

SUBSEQUENT REPORT OF:

REMEDIAL WORK

☐

ALTER CASING

☐

COMMENCE DRILLING OPNS.

☐

PLUG AND ABAN.

☒

CASING TEST AND CMT JOB

☐

OTHER:

12. Describe Proposed or Completed Operations(Clearly state all pertinent details, and give pertinent dates, including
estimated date of starting any proposed work) SEE RULE 1103.

WORK PERFORMED 10-19 THRU 10-23-92

SPOT 300' OF CMT (200 SX) F/3590-3290,(CIBP NOT SET)PLUG WILL COVER KNIGHT SERIES & PENROSE.
TAG CMT @ 3236, SPOT 25 SX CMT PLUG F/2770-2570'.

PERF 4 HOLES AT 1365', PUMP 130 SX. CMT F/1365 INSIDE 5-1/2' & 5-1/2' X 8-5/8 ANN.

TAG TOC @ 1415, PUMP INTO PERFS @ 1365, PUMP 130 SX CMT INTO PERF AT 1365'

NO BLOW ON 10-3/4. TAG CMT @ 824, PERF 4 HOLES @ 350', LOAD HOLE. ESTAB INJ

RATE INTO PERFS @ 350'. SQZ 126 SX CMT INTO FORM, 6 X 10-3/4 ANN, CIRC 47 SX

CMT TO SURFACE. CUT OFF WELLHEAD & ANCHORS & INSTALL P&A MARKERS.

CHANGE WELL STATUS TO P & A.

(CHANGE OF PROCEDURE OK'D BY OCD REP CHARLIE PERRIN WHO WAS ON LOCATION.)

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

Nita Rice

TITLE

TECHNICAL ASSISTANT

DATE:

10/27/92

TYPE OR PRINT NAME

NITA RICE

TELEPHONE NO. (915)687-7436

APPROVED BY

Charlie Perrin

TITLE

OIL & GAS INSPECTOR

DATE

JAN 14 1993

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

OCT 28 1992

OSD MOBES OFFICE