

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
310 Old Santa Fe Trail, Room 206
Santa Fe, New Mexico 87503

WELL API NO. 30-025-06954
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name Downes D
8. Well No. 1
9. Pool name or Wildcat Tubb
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3466'

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> Unsuccessful Plug Back OTHER
2. Name of Operator The Wiser Oil Company
3. Address of Operator 8115 Preston Rd., Ste 400, Dallas, TX 75225
4. Well Location Unit Letter K : 1980 Feet From The South Line and 2080 Feet From The West Line Section 32 Township 21S Range 37E NMPM Lea County

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input checked="" type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

CIBP set @ 6407'. Perf Tubb from 5958-6355' w/30 holes. Acidize Tubb w/2000 gal NEFE w/60 ball sealers. Recompletion was unsuccessful.

While on location, a decision was made to come up to the Blinebry zone. (Amended permit attached). CIBP set @ 5920'. Perf 5515-5794'. Acidize 5796-5515' (spot 11 Bbls on form). Formation was tight. Well is to be P&A'd.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Susan Hopper TITLE Agent DATE 2/20/96
TYPE OR PRINT NAME Susan Hopper TELEPHONE NO. 214-360-3522

(This space for State Use) ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT I SUPERVISOR

FEB 27 1996

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

7A Drinkard do

LED 5: 1030

