

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

2040 Pacheco St.
Santa Fe, NM 87505

WELL API NO.	30-025-06964
5. Indicate Type of Lease	STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.	
7. Lease Name or Unit Agreement Name	
Hare, J G	
8. Well No.	4
9. Pool name or Wildcat	Paddock (49210)
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	
3456' DF 3449' GR	

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER	2. Name of Operator Collins & Ware, Inc.
3. Address of Operator 508 West Wall, Suite 1200, Midland, Texas 79701	4. Well Location Unit Letter N : 660 Feet From The South Line and 1880 Feet From The West Line Section 33 Township 21S Range 37E NMMPM Lea County
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3456' DF 3449' GR	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input checked="" type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: acidize and fracture treat <input checked="" type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1/12/98 Tag PBDT at 5312', approx 8' below bottom perfs, 28' of sand fill.

1/13/98 Acidize perfs 5282 - 5304 with 1000 gals 15% Ferchek acid.

1/14/98 Fracture treat with 33,920 gals Delta - Frac and 1180 sx 20/40 white sand. Tag sand at 5146' and wash to PBDT at 5336'.

1/15/98 Run 2 3/8" tubing to 5039' with SN at 5006' and TAC at 5009' with 10 points tension. Run rods and 2" x 1 1/2" x 16' RHBC pump. Return well to production.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE [Signature] TITLE Production Supervisor DATE 2/12/98

TYPE OR PRINT NAME Dianne Sumrall TELEPHONE NO. (915) 687-3435

(This space for State Use)

APPROVED BY ORIGINAL OF [Signature] DISTRICT ATTORNEY TITLE PRODUCTION SUPERVISOR DATE FEB 19 1998

CONDITIONS OF APPROVAL, IF ANY