C i = 4i ∈ LivED S = E T i ∈ N E	NEW MEXICO OIL CONSE	ERVATION COMMISSION	Form. C=103 Supersedes Old C=102 and C=103 Effective 1===65
			5a. Indicate Type of Lease State Fee X
O HERATOR			5. State Oil & Gas Lease No.
SUNDRY NO	DTICES AND REPORTS ON 5 TO CRILL OR TO DI PEN OR PLUG B PERMIT = COMM C-101) FOR SUC	WELLS Ack to a different reservoir. • proposals.]	
	ΤΗΕR -	•	7, Unit Agreement Name
Amerada Hess Corporatio	n	· · · · · · · · · · · · · · · · · · ·	8. Farm of Lease Lame J.G. Hare
Drawer "D", Monument, N	ew Mexico 88265		9. Well tio. 5
4. Loophice of Well UNIT LETTER K 1980 THE South Line, Section		LINE AND 1980 FEET FRO	
	15, Elevation (Show whether	DF, RT, GR, etc.) 3456! DF	12. County Lea
Check Appr NOTICE OF INTER	P	ature of Notice, Report or C SUBSEQUE	ther Data NT REPORT OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK X	ALTERING CASING PLUG AND ABANDONMENT
other	one (Clearly state all pertinent det	uls and give pertinent dates includi	ne estimated date of starting any proposed

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Pulled production equipment. Ran Accoustic cement bond log from 2732' to 5432' & Neutron Lifetime log from 2750' to 5440'. Set cast iron bridge plug in 5-1/2" casing at 5440' w/cement on top. Blinebry Zone P&A. Perforated 5-1/2" casing in Paddock zone from 5278' to 5296' with 2 shots per foot. Acidized Paddock zone perfs. 5278' to 5296' with 2500 gals. 15% NE Suspension acid with Benzoic flakes and rock salt as diverter. Swab tested. Set pumping unit, ran rods & pump & srated pumping. Producing status clanged from flowing oil well in Blinebry zone to pumping oil well in Paddock zone.

SIGNED	Black	TITLE Supv r., Admin. Services	DATE
	Orin Signed in		
APPHOVED BY			DATE

Ł