

Submit 3 Copies To Appropriate District

Office

District I

1625 N. French Dr., Hobbs, NM 88240

District II

1301 W. Grand Avenue, Artesia, NM 88210

District III

1000 Rio Brazos Rd., Aztec, NM 87410

District IV

1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-103

Revised March 25, 1999

WELL API NO.
30-025-06970

5. Indicate Type of Lease

STATE ☒ FEE ☐

6. State Oil & Gas Lease No.

7. Lease Name or Unit Agreement Name:

J.N. Carson NCT-C

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH
PROPOSALS.)

1. Type of Well:

Oil Well ☒ Gas Well ☐ Other

2. Name of Operator Chevron USA, Inc.

8. Well No.

2

3. Address of Operator 15 Smith Rd. Midland, Tx 79705

9. Pool name or Wildcat
Blinebry

4. Well Location

Unit Letter A : 460 feet from the north line and 635 feet from the east line

Section 33 Township 21-S Range 37-E NMPM County Lea

10. Elevation (Show whether DR, RKB, RT, GR, etc.)

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐ CHANGE PLANS ☐

PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☒

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

1. RIH set 7" CIBP @ 5100 spot 25sx plug fr/5100 to 5000 (Blinebry) Tag @ 4911 (OK w/Gary wink)
2. Displace hole w/MLF, 9.5# Brine w/25# Gel p/BBL.
3. Spot 40sx plug fr/3800-3600(Queen)
4. Perf 4 holes @ 2900 sqz 75sx fr/2900 to 2700 (9 5/8 shoe, B-salt, Yates) Tag @ 2810 respot w/25sx Tag @ 2637 Ok w/EL w/OCD
5. Perf 4 holes @ 1400 sqz w/75sx fr/1400 to 1200 (T-salt) Tag @ 1145
6. Perf 4 holes @ 350 circ cmt (fr/7"X9 5/8"X13 3/8" csg) fr/350 to surf Tag @ surf
7. Install dry hole marker 10-21-02

Approved as to plugging of the Well Bore.

Liability under bond is retained until
surface restoration is completed.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE [Signature] TITLE MANAGER/SUNSET DATE 10-21-02

Type or print name Jimmy BAGLEY Telephone No 915 520-8758
(This space for State use)

APPROVED BY [Signature] TITLE WINK DATE FEB 11 2003

Conditions of approval: if any: WINK
OIL & GAS REPRESENTATIVE II/STAFF MANAGER

GWV