

Submit 3 Copies To Appropriate District
 Office
 District I
 1625 N. French Dr., Hobbs, NM 87240
 District II
 811 South First, Artesia, NM 87210
 District III
 1000 Rio Brazos Rd., Aztec, NM 87410
 District IV
 2040 South Pacheco, Santa Fe, NM 87505

State of New Mexico
 Energy, Minerals and Natural Resources

Form C-103
 Revised March 25, 1999

OIL CONSERVATION DIVISION
 2040 South Pacheco
 Santa Fe, NM 87505

WELL API NO. 30-025-06971
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name: J. N. CARSON (NCT-A)
8. Well No. 3
9. Pool name or Wildcat PADDOCK

SUNDRY NOTICES AND REPORTS ON WELLS
 (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE 'APPLICATION FOR PERMIT' (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
 Oil Well Gas Well Other

2. Name of Operator
Chevron U.S.A. Inc.

3. Address of Operator
P.O. Box 1150 Midland, TX 79702

4. Well Location
 Unit Letter **B** : **660** feet from the **NORTH** line and **2180** feet from the **EAST** line
 Section **33** Township **21S** Range **37E** NMPM County **LEA**

10. Elevation (Show whether DR, RKB, RT, GR, etc.)

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	MULTIPLE COMPLETION <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: <input type="checkbox"/>		OTHER: <input type="checkbox"/>	

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.

POH W/PROD EQPT. SET CIBP @ 5050'; SPOTTED 25 SX CMT ON TOP. SET CICR @ 2442'.
 PFD 200 SX CMT; DUMPED 25 SX CMT ON CICR - TAGGED @ 2375'. PERFD 4 JH 1200-1201'.
 SET CICR @ 1131'. PFD 150 SX CMT; DUMPED 25 SX CMT ON CICR - TOC @ 892'. PERFD
 4 JH @ 360'. PFD 230 SX CMT; OBTAINED RETURNS OUT 9-5/8 X 13-3/8 - ALL STAYED
 FULL OF CMT, LEAVING 7" FULL OF CMT ALSO. CUT OFF WH, INSTALL MARKER, CLEAN LOCATION.

P&A'D 6/27/01

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE J. K. Ripley TITLE REGULATORY O.A. DATE 7/9/01
 Type or print name J. K. RIPLEY Telephone No. (915) 687-7148

APPROVED BY [Signature] TITLE [Signature] DATE 10-2-01
 Conditions of approval, if any:

GWW