| UNGY AND MINEFALS OBPARTMENT   |   |
|--|---|
| L CONSERVATION L   |   |
| DISTRIBUTION DIVISIO.  |   |
| P. O. BOX 2088   | Form C-103                              |
| FILE NEW MEXICO 87501  | Revised 10-1-7                          |
| U.3.a.3.   |   |
| LAND OFFICE  | Sa. Indicate Type of Lease              |
| OPERATOR AUG 100   |   |
|  | 5. State Oil & Gas Lease No.            |
| SUNDRY NOTICES AND REPORTS ON WELLS  |   |
| USE "APPLICATION FOR PERMIT -" TPORM C-101) FOR SUCH PROPOSALS.)   |   |
| DIL CAS GAS OTHER  | 7. Unit Agreement Name                  |
| me of Operator   | Central Drinkard Unit                   |
| Chevron U.S.A. Inc.  | 8. Form or Lease Name                   |
| frees of Operator  |   |
| P.O. Box 570 Hobbs, NM 88240   | 9. Weil No.                             |
| cation of Well   | 128                                     |
|  | 10. Field and Pool, or Wildcat          |
| UNIT LETTER B PEET FROM THE NORTH LINE AND 2180  | Drinkard                                |
|  |   |
| THE East LINE, SECTION 33 TOWNSHIP 215 RANGE 37E   |   |
|  | •• VIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIII |
| () 15. Elevation (Show whether DF, RT, GR, etc.)   | 12. County                              |
| 3459   |   |
| Check Appropriate Box To Indicate Nature of Notice, Report or (<br>NOTICE OF INTENTION TO:   | Lea <u>ANNIN</u>                        |
| NOTICE OF INTENTION TO:  | Jther Data                              |
| SUBSEQUE   | NT REPORT OF:                           |
| CAN ACMEDIAL WORK  |   |
| QRARILY ARANDON  | ALTERING CASING                         |
| OR ALTER CASING  | PLUG AND ABANDONMENT                    |
| LASING FEST AND CEMENT JOB   |   |
| other polymer sqz,   | acdz                                    |
|  |   |
| acribe Proposed or Completed Operations (Clearly state all pertinent details, and successful and |   |

percise Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed pork) SEE RULE 1103.

Work performed 7/13/88 thru 7/23/88

TD: 7644

POOH w/production equipment. Pmp 45bbl FW, w/4980# 20/40 sand, estimate top of sand at 6508'. TIH tag fill at 6270'.Mix and pump pre-flush treatment. Mix and pump polymer treatment as directed (sqz 6469-6488 perfs). Allow polymer sqz to set 48 hrs. Rev. circulate wellbore clean, swabbed well dry. Spot 15% NEFE HCL acid inside tbg. Attempt to acdz at 6587, acid communicated. Attempt to acidize 6587, acid communicated. Attempt to acidize 6560-62, communicated, aborted remainder of acid job. Reverse out remaining acid. Swab well. RIH w/ 2 7/8" production tbg, to 6614', SN at 6579'. RIH w/rods and pump. Space out, hung on, load tbg w/ CBW,

| hereby certify that the information above is true and complete | e to the best of my knowledge and belief. |               |   |
|--|---|---------------|---|
| m. E. abin   | Staff Drilling Engr.                      | August 8, 198 | 8 |
| ITIONS OF ASPROVAL, IF ANY:                                    | DISTRICT 1 SUPERVISOR                     | AUG 1 2'88    |   |