

Submit 3 Copies
to Appropriate
District Office

2

State of New Mexico
Energy, Minerals and Natural Resources Department
OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

Form C-103
Revised 1-1-89

DISTRICT I

P.O. Box 1980, Hobbs, NM 88240

DISTRICT II

P.O. Drawer Dd, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, Nm 87410

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FCRM C-101) FOR SUCH PROPOSALS.)		API NO. (assigned by OCD on New Wells) 30-025-06974
1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
2. Name of Operator CHEVRON U.S.A. INC.		6. State Oil & Gas Lease No. N/A
3. Address of Operator P.O. BOX 1150 MIDLAND, TX 79702 ATTN: NITA RICE		7. Lease Name or Unit Agreement Name CENTRAL DRINKARD UNIT
4. Well Location Unit Letter H : 2080 Feet From The NORTH Line and 660 Feet From The EAST Line Section 33 Township 21S Range 37E NMPM LEA County		8. Well No. 144
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3463' KB		9. Pool name or Wildcat DRINKARD

11 Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data		
NOTICE OF INTENTION TO:		
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>		CASING TEST AND CMT JOB <input type="checkbox"/>
OTHER: <input type="checkbox"/>		OTHER: <input type="checkbox"/>
SUBSEQUENT REPORT OF:		
		ALTER CASING <input type="checkbox"/>
		PLUG AND ABAN. <input checked="" type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

WORK PERFORMED 1-28 THRU 2-2-94
PLUG #1, SET CIBP @ 6473', W/25 SX PLUG 64473-6162'.
PLUG #2, 35 SX CMT F/5294-458' (COVERS GLORIETTA)
PLUG #3, PERF @ 3650', UNABLE TO PMP INTO PERFS, OCD OK'D 25 SX PLUG F/ 3781-3470'
PERF @ 1250', OCD OK'D 80 SX CMT DN 5" THRU PERFS @ 1250 & UP 5" & 7" ANNULUS.
TOC 700' & BTM @ 1250 IN BOTH STRINGS. PERF @ 350', PMP DN 5" & CIRC UP 5 & 7" ANN.
NO CIRC UP 7" & 9-5/8 ANN. PMP 50 SX DN BTM @ 350, TOP @ SURFACE.
(9.5 PPG MUD BETWEEN ALL PLUGS)
PULL DEAD MAN ANCHORS, FILL PITS, LEVEL LOCATION, NO P&A MARKER BY SPECIAL
REQUEST & PERMISSION FROM JERRY SEXTON OF OCD.
CHANGE STATUS OF WELL TO PLUGGED AND ABANDONED.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Nita Rice TITLE TECHNICAL ASSISTANT DATE: 2/10/94

TYPE OR PRINT NAME NITA RICE TELEPHONE NO. (915)687-7436

APPROVED BY Charles Perrin TITLE OIL & GAS INSPECTOR DATE APR 05 1994
CONDITIONS OF APPROVAL, IF ANY: