

OIL CONSERVATION DIVISION

P. O. BOX 1028
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease	
State ☐	Fee ☒
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEFEED OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT TO DRILL" (FORM C-101) FOR SUCH PROPOSALS.)

OIL WELL ☐	GAS WELL ☐	OTHER - <u>Water Injection</u>
Name of Operator <u>Gulf Oil Corporation</u>		
Address of Operator <u>P. O. Box 670, Hobbs, NM 88240</u>		
Location of Well UNIT LETTER <u>E</u> , <u>1980</u> FEET FROM THE <u>North</u> LINE AND <u>660</u> FEET FROM THE <u>West</u> LINE, SECTION <u>33</u> TOWNSHIP <u>21S</u> RANGE <u>37E</u> NMPM.		

7. Unit Agreement Name <u>Central Drinkard Unit</u>
8. Farm or Lease Name
9. Well No. <u>141</u>
10. Field and Pool, or Wildcat <u>Drinkard</u>
12. County <u>Lea</u>

11. Elevation (Show whether DF, RT, GR, etc.)

3579' GL

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐
DRILL OR ALTER CASING ☐	OTHER ☐

REMEDIAL WORK ☐	ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐	PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOBS ☐	OTHER <u>Squeezed 6510-14'</u> ☒

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

POH with packer & tubing. Spot 8 sacks 10/20 sand across 6534-6590' back to 6530'. Tag top of sand at 6544', spot more 10/20 sand. Tag top of sand at 6529'. Dump cal seal on top of sand at 6529'. Tag top of plug at 6521'. Set cement retainer at 6448'. Pump into perfs 6510-14' with Class "C" cement with .5 Halad 9, squeeze to 3200#; reverse out cement. Max inj 1 BPM at 2200#, min inj 1/2 BPM at 3200#. Tag top of cement at 6443'. Drilled up retainer & 70' cement below to 6519'. Test perfs 6510-14' to 2000# 30 min., ok. Drilled cal seal plug to 6529' & reverse out frac sand to 6627'. Pump into perfs 6534-90' with water at 1 BPM at 1000#. WIH with packer on 2-3/8" tubing (replaced 14 bad joints). Circulate with GKF & set packer at 6359' with 12,000#. Put well on injection. Complete after squeezing perfs 6510-14' 10-5-80.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Elynn Stone

TITLE Area Engineer

DATE 10-7-80

Orig. Sign. by
Les C. [unclear]

PROVED BY Oil & Gas Dept.

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY: