

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease  
State  Fee

5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name Central Drinkard Unit
2. Name of Operator Gulf Oil Corporation	8. Farm or Lease Name
3. Address of Operator Box 670, Hobbs, New Mexico 88240	9. Well No. 142
4. Location of Well UNIT LETTER <u>F</u> <u>1980</u> FEET FROM THE <u>North</u> <u>1980</u> FEET FROM THE <u>West</u> <u>33</u> LINE, SECTION <u>21-S</u> TOWNSHIP <u>37-E</u> RANGE <u>37-E</u> NMPM.	10. Field and Pool, or Wildcat Drinkard
15. Elevation (Show whether D, RT, GR, etc.) 3464' GL	12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <u>Perforate additional zone and acidize. (Well is not producing).</u> <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

6615' TD.

Check depth to determine that Drinkard perforations 6560' to 6610' are open. Perforate additional Drinkard zone in 5" casing with 2, 1/2" JHPF at 6514-19', 6532-37' and 6546-51'. Treat perforations 6514' to 6610' with 6,000 gallons of 15% NE acid. Flush with water. Swab and test.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED H. J. Bruzeale TITLE Area Engineer DATE November 2, 1972

APPROVED BY John Runyan TITLE Geologist DATE NOV 6 1972

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

1 1972

OIL CONSERVATION COMM.  
HOBBES, N. M.