

Submit 3 Copies
to Appropriate
District Office

2

State of New Mexico
Energy, Minerals and Natural Resources Department
OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

Form C-103
Revised 1-1-89

DISTRICT I

P.O. Box 1980, Hobbs, NM 88240

DISTRICT II

P.O. Drawer Dd, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, Nm 87410

API NO. (assigned by OCD on New Wells)
30-025-06993

5. Indicate Type of Lease
STATE ☐ FEE ☒

6. State Oil & Gas Lease No.
N/A

7. Lease Name or Unit Agreement Name
CENTRAL DRINKARD UNIT

8. Well No.
156

9. Pool name or Wildcat
DRINKARD

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
OIL ☐ GAS ☐
WELL ☒ WELL ☐ OTHER ☐

2. Name of Operator
CHEVRON U.S.A. INC.

3. Address of Operator
P.O. BOX 1150 MIDLAND, TX 79702 ATTN: NITA RICE

4. Well Location
Unit Letter 0 : 589 Feet From The SOUTH Line and 1909 Feet From The EAST Line
Section 33 Township 21S Range 37E NMPM LEA County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)
3456' GR

11 Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTER CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABAN. ☐
CASING TEST AND CMT JOB ☐
OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including
estimated date of starting any proposed work) SEE RULE 1103.

WE PROPOSE TO:

PLUG #1, SET CIBP @ 6500', W/25 SX CMT ON TOP. (COVERS 5-1/2" SHOE)
PLUG #2, 35 SX CMT F/5020-6020' (COVERS GLORIETTA)
PLUG #3, PERF 5-1/2" CSG @ 3850, SQZ W/50 SX CMT. (COVERS 8-5/8" SHOE)
PLUG #4, PERF @ 250', SQZ W/65 SX PLUG 1150-1300' (COVERS SALT ZONE)
CIRCULATE TO SURFACE.
PLUG #5, PERF @ 250', SQZ 100 SX PLUG 350-SURFACE (COVERS 13-3/8" SHOE)
PLACE 9.5 PPG MUD BETWEEN ALL PLUGS.
PULL DEAD MAN ANCHORS, FILL PITS, LEVEL LOCATION, PLACE P&A MARKER
AND CHANGE STATUS OF WELL TO PLUGGED AND ABANDONED.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Nita Rice

TITLE TECHNICAL ASSISTANT

DATE: 8/9/93

TYPE OR PRINT NAME NITA RICE

TELEPHONE NO. (915)687-7436

APPROVED BY

Orig. Signed by
Paul Kautz
Geologist

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY

THE COMMISSION MUST BE NOTIFIED 24
HOURS PRIOR TO THE BEGINNING OF
PLUGGING OPERATIONS FOR THE G-103
TO BE APPROVED

AUG 16 1993