

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease
State ☐ Fee ☒

5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT --" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input checked="" type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER-	7. Unit Agreement Name
2. Name of Operator Amoco Production Company	8. Farm or Lease Name OWEN B
3. Address of Operator BOX 68, HOBBS, N. M. 88240	9. Well No. 1
4. Location of Well UNIT LETTER M 990 FEET FROM THE SOUTH LINE AND 330 FEET FROM THE WEST LINE, SECTION 34 TOWNSHIP 21-S RANGE 37-E NMPM.	10. Field and Pool, or Wildcat BRINKARD - OIL
15. Elevation (Show whether DF, RT, GR, etc.) 3450'	12. County LEA

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input checked="" type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input checked="" type="checkbox"/> Recomplete	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	

17. Describe the Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Paddock zone ceased production and was shut-in Dec. 1972. Propose to abandon Paddock and drill out cement and reenter to a depth of 6614(TD) and attempt completion in the Brinkard.

PADDOCK. Abandon by squeezing perfs 5120'-5284' w/120 Sx. Incon neat.

BRINKARD - Perforate intervals (various) between 6328 - 6504 w/ 2150PF + stimulate w/ 3000 gal acid & frac w/ 60000 gal Duwell wide frac + 80,000 # Sand. Evaluate and put on production.
CRJ

TD-6614'
PBD-5205'
5" CSG 6614'

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED **Ray L. Yorkum** TITLE **ADMINISTRATIVE ASSISTANT** DATE **APR 1 1974**

APPROVED BY _____ TITLE _____ DATE **APR 4 1974**

CONDITIONS OF APPROVAL, IF ANY:

04 2-AMCC-11

1- DIV
1- 5299