NO. OF COPIES RECEIVED		Form C - 103
	-	Supersedes Old
DISTRIBUTION	NEW MEXICO OI - CONSERVATION COMMISSION	C-102 and C-103 Effective 1-1-65
SANTA FE	NEW MEXICO OF L CONSERVATION COMMISSION	Friective 1-1-03
FILE		Sa. Indicate Type of Lease
U.S.G.S.	-	State Fee X
LAND OFFICE		5. State Oil & Gas Lease No.
OPERATOR		
INA MAT USE THIS FORM FOR PR	RY NOTICES AND REPORTS ON WELLS ROPOSALS TO DRILL OR TO DEEPEN (R PLUG BACK TO A DIFFERENT RESERVOIR. TION FOR PERMIT - " (FORM C-101 FOR SUCH PROPOSALS.)	
I. OIL GAS WELL WELL WELL	OTHER. DUAL COMPLETED	7. Unit Agreement Name
2. Name of Operator		8. Farm or Lease Name
AMOCO PRODUCTION O	COMPANY	OWEN B
3. Address of Operator		9. Well No.
P.O. DRAWER A, LEVELLAND, TEXA	S 79336	2
4. Lozation of Well		10. Field and Pool, or Wildcat
UNIT LETTER	980 FEET FROM THE SOUTH LINE AND 440 FEET FRO	DRINKARD - TUBB
THE WEST LINE, SECT	TION 34 TOWNSHIP 21-S RANGE 37-E NMPR	
	15. Elevation (Show whether DF, RT, GR, etc.)	12. County
	3458 DF	LEA
	Appropriate Box To Ind cate Nature of Notice, Report or O	
PERFORM REMEDIAL WORK	PLUG AND ABAN JON REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON	COMMENCE DRILLING OPNS.	PLUG AND ABANDONMENT
PULL OR ALTER CASING	CHANGE PLANS CASING TEST AND CEMENT JOB	
	OTHER TEMPORARILY A	BANDON
	[] [
OTHER		
	Operations (Clearly state all peninent details, and give pertinent dates, including	ng estimated date of starting any pronosed
17. Elescribe Proposed or Completed of work) SEE RULE 1903. On 8/13/76 plug in tubin	abandoned Dunkard zone 6382'-63 ng and set at 6547'. Opened Bake flow Jubb zone 6070'-6344'	582' by running in sleeve at
17. Describe Proposed or Completed on 173/76 On 8/13/76 plug in tubin 6360' and prompletion go	abandoned Dunkard zone 6382'-63 ng and set at 6547'. Opened Bake flow Jubb zone 6070'-6344'	582' by running in sleeve at
17. Describe Proposed or Completed and work) SEE RULE 1603. On 8/13/76 plug in tubin 6360' and completion go tompletion go 18. I hereby certify that the information of the completion go 18. I hereby certify that the information of the completion go 18. I hereby certify that the information of the completion go 18. I hereby certify that the information of the certific that the cert	abandoned Dunkard zone 6382'-63 ng and set at 6547'. Opened Bake flow Jubb zone 60'70'-6344' o as well.	582' by running or sleeve at a single
17. Describe Proposed or Completed work) SEE RULE 1903. On 8/13/76 plug in tubin 6360' and completion go tompletion go 18.1 hereby certify that the information of the completion go 18.2 MMocc-H 1-DIV	abandoned Dunkard zone 6382'-63 og and set at 6547'. Opened Bake flow Jubb zone 60'70'-6344' of as well. Jubb zone 60'70'-6344' of as well.	582' by running in sleeve at is a single
17. Describe Proposed or Completed and work) SEE RULE 1603. On 8/13/76 plug in tubin 6360' and completion go tompletion go 18. I hereby certify that the information of the completion go 18. I hereby certify that the information of the completion go 18. I hereby certify that the information of the completion go 18. I hereby certify that the information of the certific that the cert	abandoned Dunkard zone 6382'-63 ng and set at 6547'. Opened Bake flow Jubb zone 60'70'-6344' of as well. In above is true and complete to the best of my knowledge and belief. Type Type Type Type Type	DATE 8/19/76