10. C. COPIES RECEIVED]		Form C-103
DISTRIBUTION]		Supersedes Old
ANTAFE	NEW MEXICO OIL CONSI	ERVATION COMMISSION	C-102 and C-103 Effective 1-1-65
I LE	1		
U.S.G.S.	1		Sa. Indicate Type of Lease
LAND OFFICE	1		State Fee XX
OPERATOR]		5, State Oll & Gas Lease No.

(DO NOT USE THIS FORM FOR PRO USE "APPLICAT	AND TICES AND REPORTS ON DECEMBER OF PLUG BALS TO DRILL ON TO DEEPEN OF PLUG BALS	WELLS ACK TO A DIFFERENT RESERVOIR. H PROPOSALS.)	Δ
1. OIL GAS WELL WELL	OTHER-		7. Unit Agreement Name
2. Name of Operator			8, Farm or Lease Name
Gulf Oil Corporation			Mark Owen
3. Address of Operator			9. Well No.
Box 670, Hobbs, New M	exico 88240		5
4. Location of Well		· · · · · · · · · · · · · · · · · · ·	10. Field and Pool, or Wildcat
Р	660 FEET FROM THE South	660 FEET FROM	Drk & Tubb Gas
UNIT LETTER			
East	ON 34 TOWNSHIP21-S	BANGE 37-E NMPM.	Δ1111111111111111
	15. Elevation (Show whether	DF, RT, GR, etc.)	12. County
		3400' DF	Lea
16. Check	Appropriate Box To Indicate N	ature of Notice, Report or Ot	her Data
NOTICE OF I	NTENTION TO:	SUBSEQUEN	T REPORT OF:
_		_	
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON	· · · · · · · · · · · · · · · · · · ·	COMMENCE DRILLING OPNS.	PLUG AND ABANDONMENT
PULL OR ALTER CASING	CHANGE PLANS	CASING TEST AND CEMENT JOB	erf & squeezed Drk 🕅
	ا السار ا	UTHER	
OTHER		and acidized Tubb Gas	
17 Describe Despend of Completed O	pergitions (Clearly state all pertinent deta		estimated date of starting any proposed

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

6241' PB, 6545' TD.

Pulled producing equipment. Drilled Baker Model D packer loose at 6374' and pushed to 6510'. Perforated Drinkard zone in 7" casing with 2, .72" JHPF at 6394-96', 6361-63', 6306'-08' and 6267-69'. Plugged back with sand to 6417'. Attempted to frac and well communicated. Set BP at 6282' and cement retainer at 6222'. Squeezed perforations 6267-69' with 50 sacks of Class C cement. WOC 12 hours. Cleaned out to 6415'. Attempted to treat and well communicated. Set cement retainer at 6241' and squeezed Drinkard zone below retainer with 35 sacks of Class C cement. WOC 45 hours. Cleaned out to retainer at 6241'. Ran treating equipment and treated Tubb perforations 5980' to 6205' with 1500 gallons of 15% MC acid. Maximum pressure 1900#, minimum 1300#, ISIP 1200#, after 15 minutes 500#. Swabbed and tested. Pull treating equipment. Ran 2-3/8" tubing and set at 6205'. Tubb gas zone to be carried as closed in, uneconomical to produce, pending further study.

18. I hereby certify that	the information above is true and co	mplete to the best	of my knowledge and belief.	
BIGNED	Janbiah		Area Engineer	DATE August 26, 1974
APPROVED BY	Orie, Signed by Joe D. Ramey			DATE