State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 1-1-89

District Office OIL CONSERVATION DIVISION **DISTRICT I** P.O. Box 1980, Hobbs, NM 88240 WELL API NO 2040 Pacheco St. 30-025-07016 Santa Fe. NM 87505 sIndicate Type of Lease P.O. Drawer DD, Artesia, NM 88210 FEE X STATE DISTRICT III State Oil & Gas Lease No. 1000 Rio Brazos Rd., Aztec, NM 87410 SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A 7Lease Name or Unit Agreement Name DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" Marshall Com (FORM C-101) FOR SUCH PROPOSALS.) Type of Well: WELL X OTHER WELL aWell No. Name of Operator Titan Resoureces I, Inc. 5 Address of Operator Pool name or Wildcat Bling 500 West Texas, Suite 500, Midland, Texas 79701 ∠Tubb Oil & Gas (Oil)/Drinkard ₄Well Location 589 North 2051 West Feet From The **Unit Letter** Line and Feet From The Line 34 218 37E Section Township **NMPM** Lea County Range 10 Elevation (Show whether DF, RKB, RT, GR, etc. 3419' GR Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PLUG AND ABANDON PERFORM REMEDIAL WORK REMEDIAL WORK ALTERING CASING **CHANGE PLANS** COMMENCE DRILLING OPNS. **TEMPORARILY ABANDON** PLUG AND ANBANDONMENT CASING TEST AND CEMENT JOB **PULL OR ALTER CASING** OTHER: Open Additional Perfs OTHER: 12Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. 11/8/97 MIRU PU, POH rods & pump, ND wellhead, NU BOP, POH tbg. 11/9/97 Clean out sand to 5875 11/11/97 Perf 5503' - 20', 5547' - 60', 5601' - 25' & 5630' - 35' w/1 SPF (63 holes) 11/12/97 TIH pkr, profile nipple, on/off tool, workstring, test to 9000 psi. set pkr 5390', load backside w/2% KCL. prepare to frac upper Blinebry. 11/13/97 Frac Blinebry(5503'-5800') w/18,000 gal Spectra Frac 35, 36,000# 16/30 Super LC, flused 1951 gals 35# Linear gel. prepare to swab. 11/14/97 Swab two days 11/16/97 Swab, tag fill 5687', set blanking plug @ 5390', prepare to finish swabbing backside. 11/18/97 Finish swabbing, CO fill 11/19/97 CO to 5807', remove sand & ball sealers 11/20/97 CO to 5875', swab 11/21/97 Swabbing 11/22/97 Swabbing, prepare to run production equipment. 11/23/97 Return well to production.

		<u> </u>
I hereby certify that the information above is true and complete to the best of my knowledge and belief.		
SIGNATURE Shirley Melton	TITLE Engineering Tech	DATE 07-27-98
TYPE OR PRINT NAME Shirley Melton		TELEPHONE NO. (915)498-8604
(This space for State Use)		

TITLE

ORIGINAL SIGNED BY CHRIS WILLIAMS

DISTRICT | SUPERVISOR

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

3 1