

MIDLAND E & P DIVISION

WELL WORK RECOMMENDATIONS

Proposals for Well Reconditioning and Subsurface Maintenance
Workovers, Expense DD's, PB's, and Conversions

Lease: Marshall Unit Well No. 3
Field: Paddock
County: Lea State: New Mexico

RECOMMENDED PROCEDURE:

5. Shut the well in until the pressure bleeds off or for a maximum of 24 hours.
6. Swab clean up, and test the well as required.
7. Return the well to production.