

NEW MEXICO OIL CONSERVATION COMMISSION  
Santa Fe, New Mexico

MISCELLANEOUS NOTICES

Submit this notice in TRIPLICATE to the District Office, Oil Conservation Commission, before the work specified is to begin. A copy will be returned to the sender on which will be given the approval, with any modifications considered advisable, or the rejection by the Commission or agent, of the plan submitted. The plan as approved should be followed, and work should not begin until approval is obtained. See additional instructions in the Rules and Regulations of the Commission.

Indicate Nature of Notice by Checking Below

NOTICE OF INTENTION TO CHANGE PLANS		NOTICE OF INTENTION TO TEMPORARILY ABANDON WELL		NOTICE OF INTENTION TO DRILL DEEPER	
NOTICE OF INTENTION TO PLUG WELL	<input checked="" type="checkbox"/>	NOTICE OF INTENTION TO PLUG BACK		NOTICE OF INTENTION TO SET LINER	
NOTICE OF INTENTION TO SQUEEZE		NOTICE OF INTENTION TO ACIDIZE		NOTICE OF INTENTION TO SHOOT (Nitro)	
NOTICE OF INTENTION TO GUN PERFORATE		NOTICE OF INTENTION (OTHER)		NOTICE OF INTENTION (OTHER)	

OIL CONSERVATION COMMISSION  
SANTA FE, NEW MEXICO

Bunice, N.Mex.

July 14, 1953

(Place)

(Date)

Gentlemen:

Hardison

Following is a Notice of Intention to do certain work as described below at the.....

**J.C. Clower** Well No. **2** in **E**  
(Company or Operator) **21** **37** (Unit)  
**SW-34** **NE** **1/4** of Sec. **34**, T. **21**, R. **37**, NMPM., **Penrose-Skelly** Pool  
(40-acre Subdivision)  
County.

FULL DETAILS OF PROPOSED PLAN OF WORK  
(FOLLOW INSTRUCTIONS IN THE RULES AND REGULATIONS)

This well was drilled in 1939. T.D. 3740 ft. 7 O.D. pipe set at 3534 ft.  
cemented 150 sacks. 16 O.D. 99 ft. cemented. Top of anhydrite 1160.

~~1160~~ We will run tubing to 3530 ft. pump 20 sacks cement out of tubing then  
pull tubing out. We should be able to sheet 7 O.D. pipe off between 1100 and 1500 ft.  
then pull 7 O.D. up to approximately 1000 ft. run tubing back to 1150 ft. pump  
30 sacks cement out of tubing then pull tubing and 7 O.D. pipe.  
Run cement plug in top of 16 O.D. pipe with 4 in. pipe marker in top.  
Well will be filled with mud and water before plugs are set.

*Complete file missing from our record*

J.C. Clower

Approved..... JUL 17 1953....., 19.....  
Except as follows:

By.....  
Supt.

Position.....  
Send Communications regarding well to:

J.C. Clower

Approved  
OIL CONSERVATION COMMISSION  
By.....  
Title.....

Name.....  
Address.....  
Drawer 380 Bunice, N.Mex.

Oil & Gas Inspector