Submit 3 Copies to Appropriate
District Office

District II

State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 1-1-89

District I P.O. Box 1980, Hobbs, NM 88240 **OIL CONVERSATION DIVISION** Santa Fe, New Mexico 87504-2088

P.O. Box 2088

P.O. Box 1980, Hobbs, NM 88240 District III

WELL API NO. 30 - 025 - 07021

5. Indicate Type of	Lease		
	STAT	E	FEE X
6 State Oil & Gas I	ease No		

P.O. Box 1980, Hobbs, NM 88240	6. State Oil & Gas Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	O A 7. Lease Name or Unit agreement Name
1. Type of Welt: OIL GAS OTHER	OWEN
2. Name of Operator OXY USA INC.	8. Well No.
3. Address of Operator P.O. Box 50250 Midland, TX 79710	9. Pool name or Wildcat WANTZ - ABO/GRANITE WASH
4. Well Location Unit Letter P : 660 Feet From The SOUTH Line and	660 Feet From The EAST Line
Section 35 Township 21 S Range 37 E	NMPM LEA County
10. Elevation (Show whether DF, RKB, RT, GR, etc. 3,368	c.)
11. Check Appropriate Box to Indicate Nature of Notice, F	Report, or Other Data
NOTICE OF INTENTION TO: SUB	SEQUENT REPORT OF:
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK	X ALTERING CASING
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRIL	LING OPNS. PLUG AND ABANDONMENT
PULL OR ALTER CASING CASING TEST AND	D CEMENT JOB
OTHER: COMM	PROD PER ORDER DHC-850

12. Describe Proposed or Complete Operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any world SEE RULE 1103.

TD - 7524'

PBTD - 7509'

ABO - 6596' - 7155'

GRANITE WASH - 7426' - 7490'

PLEASE SEE OTHER SIDE

(Min space for State Unit) BIGINAL SIGNED BY JERRY SEXTON BISTRICT I SUPERVISOR APPROVEDBY	TITLE	FEB 05 1993
TYPE OR PRINT NAME David Stewart		TELEPHONE NO. 915 685-5717
I heatby certify that the information above is true and complete to the best of my knowledge and complete to the best of my knowledge.	me Production Accoun	tant DATE 02 01 93

Attachment C-103 OXY USA Inc. Owen #1 Sec 35 T21S R37E Lea County, New Mexico

MIRU PU, NDWH. NUBOP. POOH w/ rods, pump & tbg. RIH & tag @ 7286' (RBP@7316'), pump lo-loss w/ KCl FW, circ hole, latch onto RBP & POOH. RIH & CO to 7509', set pkr @ 7337'. Acidize Granite Wash 7426-7490' w/ 1500 gal 15% NeFe HCl acid, MaxP-1760#, MinP-1290#, AvgP-1525#, ISIP-770#, swab trace oil + 27-BLW, no show of gas. SITP-0#, POOH, RIH TAC & tbg & set @ 7494'. NDBOP, NUWH. RIH w/2" X 1-1/2" X 24' BHD pump on 86 rod str. Test well as follows:

TIME	<u>OIL</u>	WATER
24	0	23-L
24	0	29-L
24	1	40-L
24	2	43-L
24	4	16-L
24	11	11-L
24	13	14-L
24	16	11-L
24	16	10-L

NMOCD Potential Test 11/12/92 pumped @ 9 1/2 SPM & 84"STR: 22-0, 3-W, 48-G, 2182-GOR, 39.6°

WANTZ ABO - 11-0 - 38-G - 3455-GOR GRANITE WASH - 11-0 - 10-G - 909-GOR