NO. OF COPIES RECEIVED	
DISTR BUTION	s su l'Elea Sucreedes Old
SANTA F NEW MEXICO OIL CONS PRATION COMMISSION	1 - 102 and C-103 5 (testine 10)-1 -
FILE	
U.S.G.S	for the spectrum
	Fee X
OPE CR	S. G. C. Cli & Gas Lease Nc.
SUNDRY NOTICES AND REPORTS ON WELLS	Callente Cours
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEDEN DE DUCK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM (C-101) FOR JUCH PROPOSALS.)	
	7. Unit Agreement 11 time
The of Operator	
Cities Service Oil Company	P. Colores Control tomos
3. Ad iress of Operator	Owen
Box 1919 - Midland, Texas 79701	1
4. Location of Well	10. Field : Frol, or Wildort
UNIT LETTER P, 660 FEET FROM THE South LINE AND 660 FEET FROM	Und. Wantz Granite Wash
THE East LINE, SECTION 35 TOWNSHIP 21S RANGE 37E	
15. Elevation (Show whether DF, RT, GE, etc.)	
AIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIII	Lea
16. Check Appropriate Box To Indicate Nature of Notice, Report or Oth	
	REPORT OF:
PERFORM REMEDIAL WORK	ALTERING CATION
TEMPORARILY ABANDON	FURS AND ABANJONMENT
PULL OR ALTER CASING CENTRAL CHANGE PLANS CASING TEST AND CENTRAL X	
	data (se
OTHER	data X
OTHER	
othes Well completion	
OTHER	estinged any propose.
OTHER	ing from dual packer and
 OTHER	ing from dual packer and acker set @ 599h! and pull-
 OTHER	ing from dual packer and acker set @ 5994' and pull- nd loaded hole and clean-
 OTHER	ing from dual packer and acker set @ 5994' and pull- nd loaded hole and clean- ole on 3-25-76. Drilled
 OTHER	ing from dual packer and acker set @ 5994' and pull- nd loaded hole and clean- ole on 3-25-76. Drilled K-55 liner hung and cement-
 OTHER	ing from dual packer and acker set @ 5994' and pull- nd loaded hole and clean- ole on 3-25-76. Drilled K-55 liner hung and cement- & CFR-2 cement. Plug down 18 hrs. Tagged top of
 OTHER	ing from dual packer and acker set @ 59914' and pull- nd loaded hole and clean- ole on 3-25-76. Drilled K-55 liner hung and cement- & CFR-2 cement. Plug down 18 hrs. Tagged top of and washed down inside
 OTHER	ing from dual packer and acker set @ 5994' and pull- nd loaded hole and clean- ole on 3-25-76. Drilled K-55 liner hung and cement- & CFR-2 cement. Plug down 18 hrs. Tagged top of and washed down inside or 30 min Held O.K.
 OTHER Well completion OTHER Well completion OTHER Well completed Operations (Clearly state all pertinent details, and give period and the provided more) see RULE 1103. T.D. 7524' Granite Wash PBTD 7509'. Well Complete. MIRU pulling unit, unseated 1-1/2" Blinebry and 2-1/16" Drinkard tub: pulling tubing out of the hole. Ran overshot, caught and released pare ed packer and 12 Jts. of 2-1/16" tail pipe out of hole. Mixed mud and ed out frac sand fill @ 61,86 - 0.T.D. 6535'. Started drilling new how to a T.D. of 7521' Granite Wash and ran 35 Jts. (1385') 4" OD 11.35# ed @ 6138 - 7523' w/85 sacks Class C w/.5 of 1% Halad 22 and .1 of 19 @ 2:35 PM on 4-13-76. Max. pressure 1800#. Did not bump plug. WOC cement @ 6126' (12' above top of liner). Drilled 12' of soft cement of liner to 6114'. Ran 2-7/8" OD tubing and tested liner to 2000# for Tagged cement inside of 4" liner @ 7454' and drilled cement from 7151 	ing from dual packer and acker set @ 5994' and pull- nd loaded hole and clean- ole on 3-25-76. Drilled K-55 liner hung and cement- & CFR-2 cement. Plug down 18 hrs. Tagged top of and washed down inside or 30 min Held O.K. 1 - PBTD 7509'. Perfor-
 OTHER Well completion OTHER Well completed Operations (Clearly state all pertinent details, and give periods that it work) see RULE 1103. T.D. 7524' Granite Wash PBTD 7509'. Well Complete. MIRU pulling unit, unseated 1-1/2" Blinebry and 2-1/16" Drinkard tub: pulling tubing out of the hole. Ran overshot, caught and released period ed packer and 12 Jts. of 2-1/16" tail pipe out of hole. Mixed mud and ed out frac sand fill @ 61,86 - 0.T.D. 6535'. Started drilling new here to a T.D. of 7521' Granite Wash and ran 35 Jts. (1385') 4" OD 11.35# ed @ 6138 - 7523' w/85 sacks Class C w/.5 of 1% Halad 22 and .h of 1% @ 2:35 PM on 4-13-76. Max. pressure 1800#. Did not bump plug. WOC cement @ 6126' (12' above top of liner). Drilled 12' of soft cement of liner to 61141'. Ran 2-7/8" OD tubing and tested liner to 2000# for Tagged cement inside of 4" liner @ 7454' and drilled cement from 7454 ated the Granite Wash w/2-0.36" holes each @ 7426', 7428', 7430', 745 	ing from dual packer and acker set @ 5994' and pull- nd loaded hole and clean- ole on 3-25-76. Drilled K-55 liner hung and cement- CFR-2 cement. Plug down 18 hrs. Tagged top of and washed down inside or 30 min Held 0.K. 4 - PBTD 7509'. Perfor- 85'. 7436'. 7437'. 7442'.
 OTHER Well completion OTHER Well complete OTHER Woll complete OTHER Well complete OTHER Woll complete	ing from dual packer and acker set @ 5994' and pull- nd loaded hole and clean- ole on 3-25-76. Drilled K-55 liner hung and cement- CFR-2 cement. Plug down 18 hrs. Tagged top of and washed down inside or 30 min Held 0.K. 4 - PBTD 7509'. Perfor- 35', 7436', 7437', 7442', 7471'. 7476'. 7480'.
 OTHER	ing from dual packer and acker set @ 5994' and pull- nd loaded hole and clean- ole on 3-25-76. Drilled K-55 liner hung and cement- & CFR-2 cement. Plug down 18 hrs. Tagged top of and washed down inside or 30 min Held O.K. 4 - PBTD 7509'. Perfor- 85', 7436', 7437', 7442', 7471', 7476', 7480', ol @ 6010' with 2-3/8" ized Granite Wash thru
 OTHER	ing from dual packer and acker set @ 5994' and pull- nd loaded hole and clean- ole on 3-25-76. Drilled K-55 liner hung and cement- & CFR-2 cement. Plug down 18 hrs. Tagged top of and washed down inside or 30 min Held O.K. 4 - PBTD 7509'. Perfor- 85', 7436', 7437', 7442', 7471', 7476', 7480', ol @ 6010' with 2-3/8" ized Granite Wash thru es w/12 ball sealers be-
 Mell completion OTHER Well completed Operations (Clearly state all pertinent details, and give per variable to the work) SEE RULE 1103. T.D. 7524' Granite Wash PBTD 7509'. Well Complete. MIRU pulling unit, unseated 1-1/2" Blinebry and 2-1/16" Drinkard tube pulling tubing out of the hole. Ran overshot, caught and released per ed packer and 12 Jts. of 2-1/16" tail pipe out of hole. Mixed mud and ed out frac sand fill @ 6h86 - 0.T.D. 6535'. Started drilling new here of a T.D. of 752h' Granite Wash and ran 35 Jts. (1385') h" OD 11.35# ed @ 6138 - 7523' w/85 sacks Class C w/.5 of 1% Halad 22 and .h of 15 @ 2:35 PM on h-13-76. Max. pressure 1800#. Did not bump plug. WOC cement @ 6126' (12' above top of liner). Drilled 12' of soft cement of liner to 61hh'. Ran 2-7/8" OD tubing and tested liner to 2000# for Tagged cement inside of h" liner @ 7h5h' and drilled cement from 7h5h ated the Granite Wash w/2-0.36" holes each @ 7h26', 7h28', 7h30', 7h7', 7h86', 7h88' and 7h90'. Ran and set 2-7/8" OD tubing with a RTTS too OD tubing tail pipe to 7250'. Swabbed Tr. oil + 23 BLW/h hrs. Acidi perfs 7h26 - 7h90' w/1500 gals 15% HCL NE acid w/additives in 6 stage tween each stage (Total of 60 ball sealers). Max. press. h300#, min. 	ing from dual packer and acker set @ 5994' and pull- nd loaded hole and clean- ole on 3-25-76. Drilled K-55 liner hung and cement- & CFR-2 cement. Plug down 18 hrs. Tagged top of and washed down inside or 30 min Held O.K. 4 - PBTD 7509'. Perfor- 35', 7136', 7137', 7142', 7171', 7176', 7180', ol @ 6010' with 2-3/8" ized Granite Wash thru as w/12 ball sealers be- press. 2600#, good ball
 OTHER Well completion of Well completion of Well completion of Werk SEE RULE 1103. 17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give perturbations of the work) SEE RULE 1103. T.D. 7524' Granite Wash PBTD 7509'. Well Complete. MIRU pulling unit, unseated 1-1/2" Blinebry and 2-1/16" Drinkard tube pulling tubing out of the hole. Ran overshot, caught and released per ed packer and 12 Jts. of 2-1/16" tail pipe out of hole. Mixed mud and ed out frac sand fill @ 6h86 - 0.T.D. 6535'. Started drilling new hot to a T.D. of 752h' Granite Wash and ran 35 Jts. (1385') h" OD 11.35# ed @ 6138 - 7523' w/85 sacks Class C w/.5 of 1# Halad 22 and .h of 15 @ 2:35 PM on h-13-76. Max. pressure 1800#. Did not bump plug. WOC cement @ 6126' (12' above top of liner). Drilled 12' of soft cement of liner to 61h4'. Ran 2-7/8" OD tubing and tested liner to 2000# for Tagged cement inside of h" liner @ 7454' and frilled cement from 7455 ated the Granite Wash w/2-0.36" holes each @ 7426', 7428', 7430', 747', 7486', 7488' and 7490'. Ran and set 2-7/8" OD tubing with a RTTS too OD tubing tail pipe to 7250'. Swabbed Tr. oil + 23 BLW/h hrs. Acidi perfs 7426 - 7490' w/1500 gals 15% HCL NE acid w/additives in 6 stage tween each stage (Total of 60 ball sealers). Max. press. h300#, min. action but did not ball out, ISIP 1700#, 5 min SIP 500#. AIR h.8 B/M. 	ing from dual packer and acker set @ 5994' and pull- nd loaded hole and clean- ole on 3-25-76. Drilled K-55 liner hung and cement- & CFR-2 cement. Plug down 18 hrs. Tagged top of and washed down inside or 30 min Held 0.K. 4 - PBTD 7509'. Perfor- 35', 7136', 7137', 7142', 71471', 71476', 7180', ol @ 6010' with 2-3/8" ized Granite Wash thru es w/12 ball sealers be- press. 2600#, good ball Swabbed and flowed load.
 OTHER Well completed operations (Clearly state all pertinent details, and give periods and the pulling work) see Rule 1103. T.D. 7524' Granite Wash PBTD 7509'. Well Complete. MIRU pulling unit, unseated 1-1/2" Blinebry and 2-1/16" Drinkard tub pulling tubing out of the hole. Ran overshot, caught and released part of the state and 12 Jts. of 2-1/16" tail pipe out of hole. Mixed mud and ed out frac sand fill @ 6h86 - 0.T.D. 6535'. Started drilling new hot to a T.D. of 752h' Granite Wash and ran 35 Jts. (1385') h" OD 11.35# ed @ 6138 - 7523' w/85 sacks Class C w/.5 of 1# Halad 22 and .h of 15 @ 2:35 PM on h-13-76. Max. pressure 1800#. Did not bump plug. WOC cement @ 6126' (12' above top of liner). Drilled 12' of soft cement of liner to 614h'. Ran 2-7/8" OD tubing and tested liner to 2000# for Tagged cement inside of h" liner @ 7454' and drilled cement from 7451 ated the Granite Wash w/2-0.36" holes each @ 7426', 7428', 7469', 7470', 7486', 7488' and 7490'. Ran and set 2-7/8" OD tubing with a RTTS too OD tubing tail pipe to 7250'. Swabbed Tr. oil + 23 BLW/h hrs. Acidi perfs 7426 - 7490' w/1500 gals 15% HCL NE acid w/additives in 6 stage tween each stage (Total of 60 ball sealers). Max. press. h300#, min. action but did not ball out, ISIP 1700#, 5 min SIP 500#, AIR h.8 B/M. Flowed 34 BO + 8 BW/lh hrs. thru 14/64" choke, FTP 0 - 50#. Swabbed 	ing from dual packer and acker set @ 5994' and pull- nd loaded hole and clean- ole on 3-25-76. Drilled K-55 liner hung and cement- CFR-2 cement. Plug down 18 hrs. Tagged top of and washed down inside or 30 min Held O.K. 4 - PBTD 7509'. Perfor- 35', 7436', 7437', 7442', 7471', 7476', 7480', ol @ 6010' with 2-3/8" ized Granite Wash thru es w/12 ball sealers be- press. 2600#, good ball Swabbed and flowed load.
 OTHER Well completion of Well completion of Well completion of Werk SEE RULE 1103. 17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give perturbations of the work) SEE RULE 1103. T.D. 7524' Granite Wash PBTD 7509'. Well Complete. MIRU pulling unit, unseated 1-1/2" Blinebry and 2-1/16" Drinkard tube pulling tubing out of the hole. Ran overshot, caught and released per ed packer and 12 Jts. of 2-1/16" tail pipe out of hole. Mixed mud and ed out frac sand fill @ 6h86 - 0.T.D. 6535'. Started drilling new hot to a T.D. of 752h' Granite Wash and ran 35 Jts. (1385') h" OD 11.35# ed @ 6138 - 7523' w/85 sacks Class C w/.5 of 1# Halad 22 and .h of 15 @ 2:35 PM on h-13-76. Max. pressure 1800#. Did not bump plug. WOC cement @ 6126' (12' above top of liner). Drilled 12' of soft cement of liner to 61h4'. Ran 2-7/8" OD tubing and tested liner to 2000# for Tagged cement inside of h" liner @ 7454' and frilled cement from 7455 ated the Granite Wash w/2-0.36" holes each @ 7426', 7428', 7430', 747', 7486', 7488' and 7490'. Ran and set 2-7/8" OD tubing with a RTTS too OD tubing tail pipe to 7250'. Swabbed Tr. oil + 23 BLW/h hrs. Acidi perfs 7426 - 7490' w/1500 gals 15% HCL NE acid w/additives in 6 stage tween each stage (Total of 60 ball sealers). Max. press. h300#, min. action but did not ball out, ISIP 1700#, 5 min SIP 500#. AIR h.8 B/M. 	ing from dual packer and acker set @ 5994' and pull- nd loaded hole and clean- ole on 3-25-76. Drilled K-55 liner hung and cement- & CFR-2 cement. Plug down 18 hrs. Tagged top of and washed down inside or 30 min Held 0.K. 4 - PBTD 7509'. Perfor- 35', 7136', 7137', 7142', 71471', 71476', 7180', ol @ 6010' with 2-3/8" ized Granite Wash thru es w/12 ball sealers be- press. 2600#, good ball Swabbed and flowed load.
 OTHER Well completion of the hole. I.D. 7521,' Granite Wash PBTD 7509'. Well Complete. MIRU pulling unit, unseated 1-1/2" Blinebry and 2-1/16" Drinkard tub: pulling tubing out of the hole. Ran overshot, caught and released packer and 12 Jts. of 2-1/16" tail pipe out of hole. Mixed mud at ed out frac sand fill @ 61,66 - 0.T.D. 6535'. Started drilling new hot to a T.D. of 7521,' Granite Wash and ran 35 Jts. (1385') 1," OD 11.35# ed @ 6138 - 7523' w/85 sacks Class C w/.5 of 1% Halad 22 and .h of 15 @ 2:35 PM on 1-13-76. Max. pressure 1800#. Did not bump plur. WOC cement @ 6126' (12' above top of liner). Drilled 12' of soft cement of liner to 611,1'. Ran 2-7/8" OD tubing and tested liner to 2000# for Tagged cement inside of 1." liner @ 71,51,' and drilled cement from 71,51 ated the Granite Wash w/2-0.36" holes each @ 71,26', 71,28', 71,43', 71,45', 71,45', 71,65', 71,65', 71,68', 71,69', 71,71,71,71,71,71,71,71,71,71,71,71,71,7	ing from dual packer and acker set @ 5994' and pull- nd loaded hole and clean- ole on 3-25-76. Drilled K-55 liner hung and cement- & CFR-2 cement. Plug down 18 hrs. Tagged top of and washed down inside or 30 min Held O.K. 4 - PBTD 7509'. Perfor- 85', 7436', 7437', 7442', 7471', 7476', 7480', ol @ 6010' with 2-3/8" ized Granite Wash thru es w/12 ball sealers be- press. 2600#, good ball Swabbed and flowed load. 70 BO + 88 BW/11 hrs.
 OTHER Well completed operations (Clearly state all pertinent details, and give periods and the pulling work) see Rule 1103. T.D. 7524' Granite Wash PBTD 7509'. Well Complete. MIRU pulling unit, unseated 1-1/2" Blinebry and 2-1/16" Drinkard tub pulling tubing out of the hole. Ran overshot, caught and released part of the state and 12 Jts. of 2-1/16" tail pipe out of hole. Mixed mud and ed out frac sand fill @ 6h86 - 0.T.D. 6535'. Started drilling new hot to a T.D. of 752h' Granite Wash and ran 35 Jts. (1385') h" OD 11.35# ed @ 6138 - 7523' w/85 sacks Class C w/.5 of 1# Halad 22 and .h of 15 @ 2:35 PM on h-13-76. Max. pressure 1800#. Did not bump plug. WOC cement @ 6126' (12' above top of liner). Drilled 12' of soft cement of liner to 614h'. Ran 2-7/8" OD tubing and tested liner to 2000# for Tagged cement inside of h" liner @ 7454' and drilled cement from 7451 ated the Granite Wash w/2-0.36" holes each @ 7426', 7428', 7469', 7470', 7486', 7488' and 7490'. Ran and set 2-7/8" OD tubing with a RTTS too OD tubing tail pipe to 7250'. Swabbed Tr. oil + 23 BLW/h hrs. Acidi perfs 7426 - 7490' w/1500 gals 15% HCL NE acid w/additives in 6 stage tween each stage (Total of 60 ball sealers). Max. press. h300#, min. action but did not ball out, ISIP 1700#, 5 min SIP 500#, AIR h.8 B/M. Flowed 34 BO + 8 BW/lh hrs. thru 14/64" choke, FTP 0 - 50#. Swabbed 	ing from dual packer and acker set @ 5994' and pull- nd loaded hole and clean- ole on 3-25-76. Drilled K-55 liner hung and cement- & CFR-2 cement. Plug down 18 hrs. Tagged top of and washed down inside or 30 min Held 0.K. 4 - PBTD 7509'. Perfor- 35', 7136', 7137', 7142', 71471', 71476', 7180', ol @ 6010' with 2-3/8" ized Granite Wash thru es w/12 ball sealers be- press. 2600#, good ball Swabbed and flowed load.
 OTHER Well completion of the hole. I.D. 7521,' Granite Wash PBTD 7509'. Well Complete. MIRU pulling unit, unseated 1-1/2" Blinebry and 2-1/16" Drinkard tub: pulling tubing out of the hole. Ran overshot, caught and released packer and 12 Jts. of 2-1/16" tail pipe out of hole. Mixed mud at ed out frac sand fill @ 61,66 - 0.T.D. 6535'. Started drilling new hot to a T.D. of 7521,' Granite Wash and ran 35 Jts. (1385') 1," OD 11.35# ed @ 6138 - 7523' w/85 sacks Class C w/.5 of 1% Halad 22 and .h of 15 @ 2:35 PM on 1-13-76. Max. pressure 1800#. Did not bump plur. WOC cement @ 6126' (12' above top of liner). Drilled 12' of soft cement of liner to 611,1'. Ran 2-7/8" OD tubing and tested liner to 2000# for Tagged cement inside of 1." liner @ 71,51,' and drilled cement from 71,51 ated the Granite Wash w/2-0.36" holes each @ 71,26', 71,28', 71,43', 71,45', 71,45', 71,65', 71,65', 71,68', 71,69', 71,71,71,71,71,71,71,71,71,71,71,71,71,7	ing from dual packer and acker set @ 5994' and pull- nd loaded hole and clean- ole on 3-25-76. Drilled K-55 liner hung and cement- & CFR-2 cement. Plug down 18 hrs. Tagged top of and washed down inside or 30 min Held O.K. 4 - PBTD 7509'. Perfor- 85', 7436', 7437', 7442', 7471', 7476', 7480', ol @ 6010' with 2-3/8" ized Granite Wash thru es w/12 ball sealers be- press. 2600#, good ball Swabbed and flowed load. 70 BO + 88 BW/11 hrs.

CONDITIONS OF APPROVAL, IF ANY: