NO. OF COPIES RECEIVED		Form C-103
DISTRIBUTION		Supersedes Old
SANTA FE	NEW MEXICO OIL CONSERVATION COMMISSION	C+102 and C-103
FILE		Effective lele65
U.S.G.S.		5a. Indicate Type of Lease
LAND OFFICE		
OPERATOR		5. State Oil & Gas Lease No.
	······	
(DO NOT USE THIS FORM FOR PRO USE "APPLICATI	Y NOTICES AND REPORTS ON WELLS posals to drill or to deepen or plug back to a different reservoi ion for permit (form C-101) for such proposals.)	». <u>())))))))))))</u>
1. OIL GAS WELL	0THER-	7. Unit Agreement Name
2. Name of Operator		8. Farm or Lease Name
CITIES SERVICE OIL COMP	Owen	
3. Address of Operator		9. Well No.
3. Address of Operator P.O. Box 69, Hobbs, New	Mexico 88240	9. Well No.
-	Mexico 88240	2
P.O. Box 69, Hobbs, New 4. Location of Well	660 South 1980	2 10. Field and Pool, or Wildcat
P.O. Box 69, Hobbs, New 4. Location of Well UNIT LETTER 0	660 FEET FROM THE SOUTH LINE AND 1980	2 10. Field and Pool, or Wildcat Drinkard-Drinkard
P.O. Box 69, Hobbs, New 4. Location of Well UNIT LETTER 0	660 FEET FROM THE SOUTH LINE AND 1980	2 10. Field and Pool, or Wildcat Drinkard-Drinkard
P.O. Box 69, Hobbs, New 4. Location of Well UNIT LETTER 0	660 South 1980	2 10. Field and Pool, or Wildcat Drinkard-Drinkard
P.O. Box 69, Hobbs, New 4. Location of Well UNIT LETTER 0	660 FEET FROM THE SOUTH LINE AND 1980	2 10. Field and Pool, or Wildcat Drinkard-Drinkard
P.O. Box 69, Hobbs, New 4. Location of Well UNIT LETTER 0	660 FEET FROM THE SOUTH LINE AND 1980	2 10. Field and Pool, or Wildcat Drinkard-Drinkard NMPM.
P.O. Box 69, Hobbs, New 4. Location of Well UNIT LETTER	660 FEET FROM THE South 1980 N 35 TOWNSHIP 21S RANGE 37E 15. Elevation (Show whether DF, RT, GR, etc.) 3362 GR	2 10. Field and Pool, or Wildcat Drinkard-Drinkard NMPM. 12. County Lea
P.O. Box 69, Hobbs, New 4. Location of Well UNIT LETTER	660 FEET FROM THE South 1980 N 35 TOWNSHIP 21S RANGE 37E 15. Elevation (Show whether DF, RT, GR, etc.) 3362 GR Appropriate Box To Indicate Nature of Notice, Report	2 TEET FROM NMPM. 10. Field and Pool, or Wildcat Drinkard-Drinkard 12. County Lea Opt or Other Data
P.O. Box 69, Hobbs, New 4. Location of Well UNIT LETTER	660 FEET FROM THE South 1980 N 35 TOWNSHIP 21S RANGE 37E 15. Elevation (Show whether DF, RT, GR, etc.) 3362 GR Appropriate Box To Indicate Nature of Notice, Report	2 10. Field and Pool, or Wildcat Drinkard-Drinkard NMPM. 12. County Lea
P.O. Box 69, Hobbs, New 4. Location of Well UNIT LETTER	660 FEET FROM THE South 1980 N 35 TOWNSHIP 21S RANGE 37E 15. Elevation (Show whether DF, RT, GR, etc.) 3362 GR Appropriate Box To Indicate Nature of Notice, Report	2 TEET FROM NMPM. 10. Field and Pool, or Wildcat Drinkard-Drinkard 12. County Lea Opt or Other Data
P.O. Box 69, Hobbs, New 4. Location of Well UNIT LETTER	660 FEET FROM THE South 1980 N 35 TOWNSHIP 21S RANGE 37E 15. Elevation (Show whether DF, RT, GR, etc.) 3362 GR Appropriate Box To Indicate Nature of Notice, Report SUBS	2 10. Field and Pool, or Wildcat Drinkard-Drinkard NMPM. 12. County Lea Drt or Other Data SEQUENT REPORT OF: ALTERING CASING
P.O. Box 69, Hobbs, New 4. Location of Well UNIT LETTER	660 FEET FROM THE South 1980 N 35 TOWNSHIP 21S RANGE 37E 15. Elevation (Show whether DF, RT, GR, etc.) 3362 GR 3362 GR Appropriate Box To Indicate Nature of Notice, Reportention TO: SUBS PLUG AND ABANDON Remedial WORK	2 10. Field and Pool, or Wildcat Drinkard-Drinkard NMPM. 12. County Lea Det or Other Data SEQUENT REPORT OF: ALTERING CASING PLUG AND ABANDONMENT
P.O. Box 69, Hobbs, New 4. Location of Well UNIT LETTER	660 FEET FROM THE South 1980 N 35 TOWNSHIP 21S RANGE 37E 15. Elevation (Show whether DF, RT, CR, etc.) 3362 GR Appropriate Box To Indicate Nature of Notice, Report ENTION TO: SUBS PLUG AND ABANDON REMEDIAL WORK COMMENCE DRILLING OPNS.	2 I.O. Field and Pool, or Wildcat Drinkard-Drinkard NMPM. 12. County Lea Drt or Other Data SEQUENT REPORT OF: ALTERING CASING PLUG AND ABANDONMENT
P.O. Box 69, Hobbs, New 4. Location of Well UNIT LETTER	660 FEET FROM THE South 1980 N 35 TOWNSHIP 21S RANGE 37E 15. Elevation (Show whether DF, RT, GR, etc.) 3362 GR 3362 GR Appropriate Box To Indicate Nature of Notice, Report ENTION TO: SUBS PLUG AND ABANDON REMEDIAL WORK CHANGE PLANS CASING TEST AND CEMENT JQ.	2 10. Field and Pool, or Wildcat Drinkard-Drinkard Interd-Drinkard NMPM. 12. County Lea Opt or Other Data GEQUENT REPORT OF: A LTERING CASING PLUG AND ABANDONMENT

work) SEE RULE 1103.

OTD 6486 Lime, PBTD 5800. Workover complete. Well was producing 2 B0 + 0 BWPD, GOR 18167 from the Drinkard (Open hole 6407--6486). Respud 3-10-72 MIRU pulling unit. Set a CIBP @ 6386. Perf Drinkard W/1 hole per ft. @ 6370--74 & 6378--82. Ran and set 2 3/8" OD tubing @ 6383 with a packer @ 6297. Swabbed well dry. Well started flowing gas @ rate of 200 MCFPD, FTP 75 psi thru 18/64" choke. Spotted 100 gals acid across perfs (6370--6382) pressured up to 3000 psi. CIBP failed. Released packer and pushed CIBP to TD 6486. Reset packer @ 6172. Acidized perfs (6370--82) and open hole (6407--6486) with 4000 gals 15% NE acid + 8000# rock salt in 3000 gals gelled brine water as a plugging agent. Max pressure 2600 psi, min pressure 1700 ps1, AIR 5.8 B/M, ISIP vacuum. Flowed on repotential 4:80 + 3 BLW/24 hrs. FTP 50# 1" choke + gas volume 501.1 MCFPD, GOR 167033. Recompleted 3-16-72. Temporarily plugged off the Drinkard zone by setting a CIBP @ 58001. Perforated the Blinebry W/1 - 0.41" hole each ● 5504, 5517, 5525, 5527, 5529, 5531, 5554, 5563, 5579, 5596, 5619, 5645, 5652, 5661, 5670, 5688, 5696, 5739, 5742, 5750 and 5760. Ran tubing W/packer @ 5785 and pressure tested CIBP to 2200 psi. Held O.K. Reset packer @ 5337. Swabbed dry. Acidized perfs (5504--5760) W/3000 gals 15% NE acid + 32 ball sealers. Max. prace. 5400 psi, min. press. 1300 psi, AIR 2.7 B/M, ISIP 1000 psi, vacuum in 2 min. Flowed on potential 4 BO + 0 BW/24 hrs, FTP 360 psi, thru 24/64" choke, gas volume 1149 MCFPD, GOR 383000. Blinebry zone completed 3-25-72. The Drinkard zone is temporarily abandoned pending down hole commingling approval from NMOCC. This well is producing from the Blinebry formation only at this time. 18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED		TITLE _Dist. Admin. Supervisor	DATE_	March 28, 1972
APPROVED BY	Orig. Signed by John Runyan Geologist	TITLE	DATE_	MAR 30 1972

÷. .

. . : . . · ···

. --- e ·

• • · . .

<u>n† 1</u> . (نور- بر میرانداد

ាក ខេត្ត

2

۲

and a second FUL

have the OIL CONSELVATION COMM. HOBES, H. M.