

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN _____
(Other inst on re-
verse side)Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

LC 932096 a

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

MMPU

8. FARM OR LEASE NAME

Lockhart A-35

9. WELL NO.

3

10. FIELD AND POOL, OR WILDCAT

Drinkard & Hubb Pools11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA**35-213-37E**

12. COUNTY OR PARISH

Lea

13. STATE

N. M.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☒ GAS WELL ☒ OTHER ☐	JAN 7 10 30 AM '64	
2. NAME OF OPERATOR	Continental Oil Company	
3. ADDRESS OF OPERATOR	Box 460, Hobbs, New Mexico	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface	660' FWL & 1980' FWL, Section 35-213-37E, Lea County, New Mexico	
14. PERMIT NO.	15. ELEVATIONS (Show whether DF, RT, GR, etc.)	
	3388 DF	

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐FRACTURE TREAT ☐SHOOT OR ACIDIZE ☐REPAIR WELL ☐(Other) **Squeeze & Perforate** ☒PULL OR ALTER CASING ☐MULTIPLE COMPLETE ☐ABANDON* ☐CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐FRACTURE TREATMENT ☐SHOOTING OR ACIDIZING ☐(Other) ☐REPAIRING WELL ☐ALTERING CASING ☐ABANDONMENT* ☐(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

To increase the production rate from the Lockhart A-35 No. 3 and increase ultimate recovery from the Drinkard zone, it is proposed to squeeze the present perforations and perforate and treat the upper Drinkard.

Procedure: Squeeze the existing Drinkard perms. w/75 sacks. Perforate intervals 6397, 6400, 6405, 6421, 6426, 6444, 6449, 6460, 6464, & 6482 w/1 JSPP. Treat w/1,500 gals. of acid and a 16,000 gal. sand frac.

Your approval of this work is requested.

APPROVED

JAN 3 1964

E. G. HUBBLE
ACTING DISTRICT ENGINEER

18. I hereby certify that the foregoing is true and correct

SIGNED _____

TITLE **Assist. Dist. Manager**DATE **1-3-64**

(This space for Federal or State office use)

APPROVED BY _____

TITLE _____

DATE _____

CONDITIONS OF APPROVAL, IF ANY:

USGS (5) NMOC (2) ABS

PAN AM HOBBS (3) ATLANTIC ROS (2) CALIF. HOUSTON (1) MIDLAND (1)

*See Instructions on Reverse Side

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.