

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT  
N.M. Oil Cons. Division  
P.O. Box 1980  
Hobbs, NM 88241

FORM APPROVED

Report Bureau No. 1004-0135

Expires: March 31, 1993

5. Lease Designation and Serial No.

LC032096A/B

6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement Designation

8. Well Name and No.

Lockhart #35  
Well #3

9. API Well No.

30-025-07032  
30-025-07034  
34

10. Field and Pool, or Exploratory Area

Blaine Oil & Gas

11. County or Parish, State

LEA, NM

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.  
Use "APPLICATION FOR PERMIT -" for such proposals

SUBMIT IN TRIPLICATE

1. Type of Well

☐ Oil Well ☒ Gas Well ☐ Other

2. Name of Operator

CONOCO INC.

3. Address and Telephone No.

684-6381  
10 DESTA DR. STE 100W, MIDLAND, TX. 79705 (915) 686-5424

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

SURFACE: 880 FNL & 1980 FWL  
TD: Sec 35, T21 S, R37E

1980 FNL, 660 FEL  
1980 W & 660 E  
Unit H  
acc

12. CHECK APPROPRIATE BOX(es) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

- ☐ Notice of Intent  
☒ Subsequent Report  
☐ Final Abandonment Notice

TYPE OF ACTION

- ☐ Abandonment  
☒ Recompletion  
☐ Plugging Back  
☐ Casing Repair  
☐ Altering Casing  
☐ Change of Plans  
☐ New Construction  
☐ Non-Routine Fracturing  
☐ Water Shut-Off  
☐ Conversion to Injection  
☐ Dispose Water

@ Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

5-15-96: Ran in hole with production tubing and set seating nipple @ 5496'. Ran in hole with pump and rods load and test tubing, return well to production.

Sundry notice submitted on 7-3-96 did not reflect that part of a retrievable bridge plug remained in the hole @ 5598' and was not on the schematic of wellbore. Blaine perfs producing only.

ACCEPTED FOR RECORD

OCT 24 1996

BLM

14. The /

Signed

Title

Ann E. Ritchie  
REGULATORY AGENT

Date 10-14-96

(This space for Federal or State office use)

Approved by

Title

Date

Conditions of approval, if any.