

Albuquerque
P.O. Box 1980, Hobbs, NM 88240

Albuquerque
P.O. Drawer 80, Azusa, NM 88110

Albuquerque
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2038
Santa Fe, New Mexico 87504-2038

WELL APT. NO.

30-025-07044

1. Indicate Type of Lease

STATE ☒ FEE ☐

2. State Oil & Gas Lease No.

E-11614

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

3. Lease Name or Unit Agreement Name

State 367

1. Type of Well:

Oil

Well ☒

Gas

Well ☐

Other ☐

2. Name of Operator

CROSS TIMBERS OPERATING COMPANY

3. Well No.

2

4. Address of Operator

P. O. Box 52070 Midland, Texas 79710-2070

5. Pool Name or Field

Drinkard/Blinebry Oil and Gas

6. Well Location

Unit Later L : 660 Feet From The West Line and 1980 Feet From The South Line

Section 36

Township 21S

Range 37E

Meridian NMGM

Lea

County

10. Elevation (Show whether CF, RCL, RT, GR, etc.)

3,376' DF

II. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☒

PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

PULL OR ALTER CASING ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐

ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐

PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

12. Describe Proposed or Completed Operations (Check only one box, and give pertinent details, including estimated date of starting any proposed work) SEE RULE 1101.

Propose to add perfs in presently producing Blinebry Zone and treat new perfs with acid and sand frac. Well is presently DHC under Order R-6783.

1. Rig up. Install BOP. POOH w/rods & pmp. POOH w/2-3/8" prod tbg.

2. Perforate Blinebry fr/5,540'-5,570' @ 1 jsfp.

3. RIH w/RBP & pkr on 2-7/8" tbg. Set RBP @ approx 5,620' & pkr @ 5,400'. Acidize Blinebry perfs fr/5,540'-5,570' w/3,000 gals 15% NEFE HCL. Swab.

4. Fracture Blinebry perfs fr/5,540'-5,570' w/21,000 gals and 162,000 lbs 20/40 sand. Swab.

5. POOH w/RBP & pkr & 2-7/8" tbg.

6. RIH w/2-3/8" production tbg. Run rods & pmp. Return to prod.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

Ray F. Martin

TITLE

Operations Engineer

DATE

9-2-94

TYPE OR PRINT NAME

TELEPHONE NO.

(This space for State Use) ORIGINAL SUBMITTED BY

OW - 444444
FIELD REPRESENTATIVE

SEP 07 1994

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

REMOVED

SEP - 6 1994

OFFICE