

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

HOBBS OFFICE O. C. C.
NEW MEXICO OIL CONSERVATION COMMISSION

FEB 7 7 34 AM '67

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		7. Unit Agreement Name
2. Name of Operator PAN AMERICAN PETROLEUM CORPORATION		8. Farm or Lease Name STATE TRACT 13
3. Address of Operator BOX 68, HOBBS, N. M. 88240		9. Well No. 8
4. Location of Well UNIT LETTER <u>D</u> , <u>990</u> FEET FROM THE <u>NORTH</u> LINE AND <u>660</u> FEET FROM THE <u>WEST</u> LINE, SECTION <u>36</u> TOWNSHIP <u>21-S</u> RANGE <u>37-E</u> N.M.P.M.		10. Field and Pool, or Wildcat BLINEBRY-OIL
15. Elevation (Show whether DF, RT, GR, etc.) <u>3379' R.D.B.</u>		12. County <u>LEA</u>

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. SEE RULE 1103.)

In accordance w/ Form C-103 submitted 11-30-66,
well P & A as follows:
Pulled 2" tubing from 2248'. Shot and pulled
7" casing from 2205'. Shot 9 7/8" at intervals
1005, 740, 647 and pulled from 612'. Cement
plugs - 75 sq @ 2200', 50 sq @ 620', 50 sq @ 360',
10 sq. @ Surface & Erected P & A marker.
Made final cleanup and restored
ground to contour.

P & A Comp. 1-25-67

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED [Signature] TITLE AREA SUPERINTENDENT DATE 2-1-67

APPROVED BY [Signature] TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY: