

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	
7. Unit Agreement Name	
8. Farm or Lease Name	
Fred Turner	
9. Well No.	
2	
10. Field and Pool, or Wildcat	
West Nadine (Blinebry)	
12. County	
Lea	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>
2. Name of Operator
Crown Central Petroleum Corporation
3. Address of Operator
4000 N. Big Spring, Suite 213, Midland, TX 79705
4. Location of Well
UNIT LETTER <u>0</u> , <u>660</u> FEET FROM THE <u>South</u> LINE AND <u>1980</u> FEET FROM THE <u>East</u> LINE, SECTION <u>6</u> TOWNSHIP <u>20S</u> RANGE <u>38E</u> NMPM.
15. Elevation (Show whether DF, RT, GR, etc.)
3568' - GL

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input checked="" type="checkbox"/> Completion

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1703.

5/8 - 23/86 Drilled out F.C.'s and cement, perforate Blinebry @ 5880', 84, 88, 94, 5938', 64, 78, 80, 6036', 38, 51, 53, 69, 74 with 3-1/8" csg. gun (14 holes, 1 jspf). Ran 2-3/8" tubing and pkr. Acidized with 2000 gal. 15% NEFE acid @ 3 BPM and 3400 psi. Fraced down 4-1/2" csg. with 37,000 gallons 40 lb. X-link water and 54,000 lbs. 20-40 sand @ 26 BPM and 3600 psi. Ran 76 rod string, set 160 unit, now pumping load plus trace oil.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED K.K. Kirby TITLE Petroleum Engineer

DATE 5/28/86

ORIGINAL SIGNED BY JERRY SEXTON

APPROVED BY DISTRICT SUPERVISOR

TITLE _____

DATE JUN 2 1986

CONDITIONS OF APPROVAL, IF ANY: