

DISTRICT I

P.O. Box 1980, Hobbs, NM 88241

DISTRICT II

P.O. Box Drawer DD, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

2040 Pacheco St.
Santa Fe, NM 87505

WELL API NO. 30-025-07780
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil / Gas Lease No.
7. Lease Name or Unit Agreement Name Fred Turner Jr. "B"
8. Well No. 1
9. Pool Name or Wildcat West Nadine -Tubb (47530)

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER	
2. Name of Operator Amerada Hess Corporation	
3. Address of Operator P.O. Box 840, Seminole, TX 79360	
4. Well Location Unit Letter <u>F</u> : <u>1980</u> Feet From The <u>North</u> Line and <u>1980</u> Feet From The <u>West</u> Line Section <u>17</u> Township <u>20S</u> Range <u>38E</u> NMPM <u>Lea</u> COUNTY	
10. Elevation (Show whether DF, RKB, RT,GR, etc.)	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input checked="" type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPERATIONS <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>		CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: <input type="checkbox"/>		OTHER: <input type="checkbox"/>	

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Plan to MIRU pulling unit. Remove wellhead, install BOP & TOH w/pkr. TIH w/drilling bailer, knock out CIBP at 6510', drilling & pushing to 7000'. TIH w/3-1/8" csg. guns loaded w/3 SPF, total 66 holes, & perf. additional Tubb Zone perms. at following intervals: 6518' - 6519', 6528' - 6529', 6544' - 6545', 6601' - 6603', 6652' - 6654', 6658' - 6659', 6662' - 6663', 6666' - 6670', 6677' - 6678', 6681' - 6683', 6686' - 6689', & fr. 6694' - 6697'. Acidize Tubb Zone perms. fr. 6518' - 6697' w/4500 gal. 15% HCL acid. Re-run tbg. Remove BOP & install wellhead. TIH w/pump & rods & begin pumping fr. Blinebry/Tubb Zones.

Well Downhole Commingled in West Nadine Paddock-Blinebry (47400), & West Nadine-Tubb (47530) by Administrative Order DHC-2819.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Roy L. Wheeler, Jr. TITLE Bus. Svc. Spec. II DATE 05/20/2002

TYPE OR PRINT NAME Roy L. Wheeler, Jr. TELEPHONE NO. 915-758-6778

(This space for State Use)

APPROVED BY _____ TITLE _____ DATE MAY 22 2002

CONDITIONS OF APPROVAL, IF ANY: