<u>District I</u> 1625 N. French Dr., Hobbs, NM 88240 <u>District II</u>				Ene	-	tate of New	rces	Form C-101 Revised March 17, 1999						
811 South First, Artesia, NM 88210 <u>District III</u> 1000 Rio Brazos Road, Aztec, NM 87410 <u>District IV</u> 2040 South Pacheco, Santa Fe, NM 87505					Conservatio 2040 South Santa Fe, NI	Pache	20	Submit to appropriate District Office State Lease - 6 Copies Fee Lease - 5 Copies AMENDED REPORT						
APPLI	CATIC	ON FOR	PERMIT 7	TO DR	ILL, I	RE-ENTEI	R, DE	EPEN,	PLUGBAC	CK)OR	ADD	A ZON	Æ	
	1	Operator Name a		NTER, DEEPEN, PLUGBACK) OR ADD A ZONE										
Amerada P.O.B				³ API Number										
				⁵ Property Name					30-025-0	07783 ⁶ Well No.				
Property Code -25386 123				M. J. Raley				<u> </u>	1					
['] Surface Location												·		
UL or lot no.	Section	U U U U		Lot Idn		Feet from the		South line	Feet from the	East/We				
D	17	205	38E				660 North		660	West Le		Lea		
Proposed Bottom Hole Location II Different From Surface														
UL or lot no.	Section	n Township Range		Lot Idn		Feet from the	North/:	South line	Feet from the	East/Wo	est line	County		
⁹ Proposed Pool 1 ¹⁰ Proposed Pool 2														
Nadine Paddock Blinebry West (47400)														
Work 1		¹² Well Type Co	13 Cable/Rotary	/Rotary ¹⁴ Lease Type Code ¹⁵ Ground Level Eleva						tion				
Р			0						P		3573 ' DF			
¹⁶ Multiple ¹⁷ Propos				Depth ¹⁸ For Bline					¹⁹ Contractor			-25-51		
L		I	²¹ P	ropose		ing and Cen	nent P	rogram	, <u></u> ,		* *			
Hole Size Ca			ing Size		Setting D		Sacks of C	E	Estimated TOC					
17-1/4"		<u> </u>	13-3/8"		36#		295'		200 Sks.		Previously Ran			
11"			8-5/8"		24 & 32#		3678'		1500 Sks.			11	11	
7-7/8"		5-1/2	5-1/2"		15.5 & 17#		9230'		600 Sks.			11	н	
Describe the proposed program. If this application is to DEEPEN or PLUG BACK, give the data on the present productive zone and proposed new productive zone. Describe the blowout prevention program, if any. Use additional sheets if necessary. Warren McKee Simpson Zone perfs. fr. 9104' - 9175' TA'd with CIBP set at 9050'. (TD: 9240') Plan to MIRU pulling unit. Remove wellhead & install BOP. Run USIT or Cast V log fr. 7500' - 5500'. TIH w/CIBP set at 6500'. Press. test csg. to 1000 PSI. If necessary, perforate & cement squeeze around Blinebry Zone fr. 5900'-6430'. Perf. Blinebry Zone using 4" csg. gun w/3 SPF at following intervals: 5948'-5950', 6042'-6046', 6128'-6129', 6180'-6181', 6235'-6237', 6271'-6273', & 6324'-6327'. Acid ze Blinebry Zone perfs. fr. 5948'-6327' w/4000 gal. 15% HCL acid. CONTINUED OVER														
²³ I hereby certify that the information given above is true and complete to the best of my knowledge and belief,							OIL CONSERVATION DIVISION							
Signature: Kay Willing							Approved by:							
Printed name: Roy L. Wheeler, Jr.							Title:							
Title:	ec, II	· · · · · ·		Appro	Approval Date: Expiration Date:									
			Phone:		Condii	Conditions of Approval:								
2-28-2000			915 758-6778			Attach	Attached							
		Qi val	~~V											

アンシ

Frac treat Blinebry Zone perfs. fr. 5948' - 6327' w/200,000# 16/30 sand in 70,000 gal. 35# XL Borate Gel. TIH w/prod. eqpt. & monitor production.

(P. C. S. V.G.C.)