

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease	State <input checked="" type="checkbox"/> <u>Federal</u> <input type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS	
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)	
1. <input type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER <u>Injection</u>	7. Unit Agreement Name
2. Name of Operator <u>Conoco Inc.</u>	8. Farm or Lease Name <u>Semur Permian</u>
3. Address of Operator <u>P.O. Box 460 - Hobbs, New Mexico 88240</u>	9. Well No. <u>31</u>
4. Location of Well UNIT LETTER <u>C</u> , <u>660</u> FEET FROM THE <u>north</u> LINE AND <u>1980</u> FEET FROM THE <u>west</u> LINE, SECTION <u>19</u> TOWNSHIP <u>20S</u> RANGE <u>38E</u> NMPM.	10. Field and Pool, or Wildcat <u>Skaggs Crayling</u>
15. Elevation (Show whether DF, RT, GR, etc.)	12. County <u>Dea</u>

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data			
NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

MIRU. POOH w/injection equipment. Clean out to 3912'.  
Acidize OH w/4500 gals 15% HCL & 250 gals Unichem  
425. Run injection equipment. Place on injection. Run  
injection profile on 7/26/88.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.			
SIGNED <u>Jerry Sexton</u>	TITLE <u>Administrative Supervisor</u>	DATE <u>9/13/88</u>	
ORIGINAL SIGNED BY JERRY SEXTON DISTRICT I SUPERVISOR		DATE <u>SEP 20 1988</u>	
APPROVED BY	TITLE	DATE	
CONDITIONS OF APPROVAL, IF ANY: <u>none</u>			