DISTRIBUTION			Form C-103 Supersedes Old
SANTA FE	NEW M	EXICO OIL CONSERVATION COMMISSION	C-102 and C-103
ř.LE		The second secon	Effective 1-1-65
J.3.0,8.			5a. Indicate Type of Lease
LAND OFFICE			State Fee A
OPERATOR			5. State Oil & Gas Lease No.
(DO NOT USE THIS FORM FO	NDRY NOTICES AND R PROPOSALS TO DRILL OR T	REPORTS ON WELLS O DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIF ORM C-101) FOR SUCH PROPOSALS.	
weet ch weet	OTHER-		7. Unit Agreement Name
Amorada Hess	Corporation		8. Farm or Lease Name B.M. Marcus
Drawer "D",	Monument, New Me	exico 88265	9. Well No.
4.1. Cation of Well			10. Field and Pool, or Wildcat
		North 1980	Skaggs Grayourg
THE WOST LINE, S		OWNSHIP 20-S RANGE 38-E	нмри.
	15. Elevan	ion (Show whether DF, RT, GR, etc.)	12. County Lea
Che-	ck Appropriate Box	To Indicate Nature of Notice, Repor	
NOTICE O	F INTENTION TO:	subs	EQUENT REPORT OF:
POWEDRM REMODIAL WORK	PLUG	AND ABANDON REMEDIAL WORK	ALTERING CASING
NOCHABLY ABANDON		COMMENCE DRILLING OPNS.	PLUG AND ABANDONMENT
PULL OR ALTER CASING	CHAN		
		GE PLANS CASING TEST AND CEMENT JOB	
Legisla .		OTHER	
отнак		OTHER	
	d Operations (Clearly stat	The way was comen age	
Plugged and al	bandoned as foll bridge plug in	e all pertinent details, and give pertinent dates,	including estimated date of starting any propose
Plugged and all Set cast iron Top of dement Out 4-1/2" cas	bandoned as foll bridge plug in at 3665'. sing at 3100'.	othere all pertinent details, and give pertinent dates,	including estimated date of starting any propose th 4 sx. cement on plug.
Plugged and al Set cast iron Out 4-1/2" cast Spoused 1,0 sx.	bandoned as foll bridge plug in at 3665'. sing at 3100'. 050' to 3150'. . cement plug fr	oTHER e all pertinent details, and give pertinent dates, LOWS: 4-1/2" OD casing at 3700' with Spotted 40 sx. cement plug in com 1650' to 1750'.	including estimated date of starting any propose th 4 sx. cement on plug.
Plugged and al Set cast iron Ter of dement Cast from 30 Spoused 1,0 sx. Spoused 20 sx.	bandoned as foll bridge plug in at 3665'. sing at 3100'. 050' to 3150'. . cement plug fr . cement plug fr	e all pertinent details, and give pertinent dates, Lows: 4-1/2" OD casing at 3700' with Spotted 40 sx. cement plug in com 1650' to 1750'. com surface to 60'.	including estimated date of starting any propose th 4 sx. cement on plug.
Plugged and al Set cast iron Top of cament Cast 4-1/2" cas cast if cast from 30 Spoused 10 sx. Spoused 9.5# miles	bandoned as foll bridge plug in at 3665'. sing at 3100'. 050' to 3150'. . cement plug fr . cement plug fr	oTHER e all pertinent details, and give pertinent dates, LOWS: 4-1/2" OD casing at 3700' with Spotted 40 sx. cement plug in com 1650' to 1750'. com surface to 60'. bove plugs while abandoning.	including estimated date of starting any propose th 4 sx. cement on plug.
Plugged and al Set cast iron Top of cament Cast 4-1/2" cas cast if cast from 30 Spoused 10 sx. Spoused 9.5# miles	bandoned as foll bridge plug in at 3665'. sing at 3100'. 050' to 3150'. . cement plug fr . cement plug fr ud between the a	oTHER e all pertinent details, and give pertinent dates, LOWS: 4-1/2" OD casing at 3700' with Spotted 40 sx. cement plug in com 1650' to 1750'. com surface to 60'. bove plugs while abandoning.	including estimated date of starting any propose th 4 sx. cement on plug.
Plugged and al Set cast iron Top of cament Cast 4-1/2" cas cast if cast from 30 Spoused 10 sx. Spoused 9.5# miles	bandoned as foll bridge plug in at 3665'. sing at 3100'. 050' to 3150'. . cement plug fr . cement plug fr ud between the a	oTHER e all pertinent details, and give pertinent dates, LOWS: 4-1/2" OD casing at 3700' with Spotted 40 sx. cement plug in com 1650' to 1750'. com surface to 60'. bove plugs while abandoning.	including estimated date of starting any propose th 4 sx. cement on plug.
Plugged and al Set cast iron Top of cament Cast 4-1/2" cas cast if cast from 30 Spoused 10 sx. Spoused 9.5# miles	bandoned as foll bridge plug in at 3665'. sing at 3100'. 050' to 3150'. . cement plug fr . cement plug fr ud between the a	oTHER e all pertinent details, and give pertinent dates, LOWS: 4-1/2" OD casing at 3700' with Spotted 40 sx. cement plug in com 1650' to 1750'. com surface to 60'. bove plugs while abandoning.	including estimated date of starting any propose th 4 sx. cement on plug.
Plugged and al Set cast iron Top of cament Cast from 30 Spoused 10 sx. Spoused 9.5# miles	bandoned as foll bridge plug in at 3665'. sing at 3100'. 050' to 3150'. . cement plug fr . cement plug fr ud between the a	oTHER e all pertinent details, and give pertinent dates, LOWS: 4-1/2" OD casing at 3700' with Spotted 40 sx. cement plug in com 1650' to 1750'. com surface to 60'. bove plugs while abandoning.	including estimated date of starting any propose th 4 sx. cement on plug.
Plugged and al Set cast iron Top of cament Cast 4-1/2" cas cast if cast from 30 Spoused 10 sx. Spoused 9.5# miles	bandoned as foll bridge plug in at 3665'. sing at 3100'. 050' to 3150'. . cement plug fr . cement plug fr ud between the a	oTHER e all pertinent details, and give pertinent dates, LOWS: 4-1/2" OD casing at 3700' with Spotted 40 sx. cement plug in com 1650' to 1750'. com surface to 60'. bove plugs while abandoning.	including estimated date of starting any propose th 4 sx. cement on plug.
Plugged and al Set cast iron Top of cament Cast 4-1/2" cas cast if cast from 30 Spoused 10 sx. Spoused 9.5# miles	bandoned as foll bridge plug in at 3665'. sing at 3100'. 050' to 3150'. . cement plug fr . cement plug fr ud between the a	oTHER e all pertinent details, and give pertinent dates, LOWS: 4-1/2" OD casing at 3700' with Spotted 40 sx. cement plug in com 1650' to 1750'. com surface to 60'. bove plugs while abandoning.	including estimated date of starting any propose th 4 sx. cement on plug.
Plugged and al Set cast iron Top of cament Cast 4-1/2" cas cast if cast from 30 Spoused 10 sx. Spoused 9.5# miles	bandoned as foll bridge plug in at 3665'. sing at 3100'. 050' to 3150'. . cement plug fr . cement plug fr ud between the a	oTHER e all pertinent details, and give pertinent dates, LOWS: 4-1/2" OD casing at 3700' with Spotted 40 sx. cement plug in com 1650' to 1750'. com surface to 60'. bove plugs while abandoning.	including estimated date of starting any propose th 4 sx. cement on plug.
Plugged and al Set cast iron Ter of dement Cast 4-1/2" cas cast from 30 Spouced 10 sx. Spouced 20 sx. Purped 9.5# m. Installed 4.1 of	bandoned as foll bridge plug in at 3665'. sing at 3100'. 050' to 3150'. cement plug fr. cement plug frud between the adry hole marker.	e all pertinent details, and give pertinent dates, LOWS: 4-1/2" OD casing at 3700' with Spotted 40 sx. cement plug in rom 1650' to 1750'. rom surface to 60'. bove plugs while abandoning. Well P&A.	including estimated date of starting any propose th 4 sx. cement on plug.
Plugged and al Set cast iron Ter of dement Cast 4-1/2" cas cast from 30 Spouced 10 sx. Spouced 20 sx. Purped 9.5# m. Installed 4.1 of	bandoned as foll bridge plug in at 3665'. sing at 3100'. 050' to 3150'. cement plug fr. cement plug frud between the adry hole marker.	e all pertinent details, and give pertinent dates, LOWS: 4-1/2" OD casing at 3700' with Spotted 40 sx. cement plug in rom 1650' to 1750'. rom surface to 60'. Bove plugs while abandoning. Well P&A.	including estimated date of starting any propose the 4 sx. cement on plug. In and out bottom 4-1/2"
Plugged and al Set cast iron Ter of dement Cast 4-1/2" cas cast from 30 Spouced 10 sx. Spouced 20 sx. Purped 9.5# m. Installed 4.1 of	bandoned as foll bridge plug in at 3665'. sing at 3100'. 050' to 3150'. cement plug fr. cement plug frud between the adry hole marker.	e all pertinent details, and give pertinent dates, LOWS: 4-1/2" OD casing at 3700' with Spotted 40 sx. cement plug in rom 1650' to 1750'. rom surface to 60'. bove plugs while abandoning. Well P&A.	including estimated date of starting any propose the 4 sx. cement on plug. In and out bottom 4-1/2"
Plugged and al Set cast iron Ter of dement Cast 4-1/2" cas cast from 30 Spouced 10 sx. Spouced 20 sx. Purped 9.5# m. Installed 4.1 of	bandoned as foll bridge plug in at 3665'. sing at 3100'. 050' to 3150'. cement plug fr. cement plug frud between the adry hole marker.	e all pertinent details, and give pertinent dates, LOWS: 4-1/2" OD casing at 3700' with Spotted 40 sx. cement plug in rom 1650' to 1750'. rom surface to 60'. Bove plugs while abandoning. Well P&A.	including estimated date of starting any propose the 4 sx. cement on plug. In and out bottom 4-1/2"