

STATE _____

FARM F. Turner WELL NO. 1

Sec. 20 T. 20 R. 32 AREA _____

660 N. _____ E. _____ S. 660 W.

Sec. _____ Blk. _____ Survey _____

SPUD 2/6 37 COMP. _____ T. D. _____ ELEV. _____

CONTRACTOR W. J. Smith TOOLS _____

SHOT_____

ACID _____ Gal. _____

ACID _____ Gal. _____

[illegible]

T. An. _____ OPEN _____ bbl. OIL _____ cu.ft. GAS _____

T. S. _____ TUBING _____ bbl. OIL _____ cu. ft. GAS _____

B. S. _____ RETEST _____

T. Br. L. _____

R. Sd. _____

T. Wh. L. _____ PRESSURE: CASING _____ TUBING _____

T. Del. L. _____	REMARKS: _____	—TUBING—
------------------	----------------	----------

T. Del Sd. _____

CASING:

Size	Depth	Cement
------	-------	--------

[illegible]

--	--	--

[illegible][illegible]

[illegible]

—TUBING—

011 011

6-1 3/5 3 R x 2 2/10 and
5/8 3/10 5.

6-29 TD 4072 +
to testing
snab 12 per ka
1 per ka

7-6 TD 4072
2800 feet below sea level

P + a

[illegible]