

Form 9-331a  
(Feb. 1951)

**DUPLICATE**


(SUBMIT IN TRIPLICATE)

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

Land Office Las Cruces

Lease No. 80425 (1)

Unit Warren



**SUNDRY NOTICES AND REPORTS ON WELLS**

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....	
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF REDRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....	
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....	
NOTICE OF INTENTION TO ABANDON WELL.....		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Warren Unit B-27 No. 1

Hobbs, New Mexico

June 5, 1951

Well No. 1 is located 1900 ft. from N line and 660 ft. from E line of sec. 27

N 1/4 Sec. 27

(1/4 Sec. and Sec. No.)

20-S

(Twp.)

10-E

(Range)

S. 14. E. 1.

(Meridian)

Wildcat

(Field)

Lea

(County or Subdivision)

New Mexico

(State or Territory)

The elevation of the derrick floor above sea level is 3552 ft.

**DETAILS OF WORK**

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudlogging jobs, cementing points, and all other important proposed work)

Set 5 1/2" casing at 7775' with 943 sacks cement. Plug down 4:00 P.M. 5-25-51.  
Top of cement by temperature survey 3632'.

Moved in reverse circulation rig and on 5-31-51 tested casing with 1500# for 30 mins., final pressure 1495#. Drilled out cement to 7773' and tested casing with 1500# for 30 mins., final pressure 1490#.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Continental Oil Company

Address Box 66

Hobbs, New Mexico

By [Signature]

Title District Superintendent

020000  
020000  
020000

3

020000 020000 020000 020000 020000 020000 020000 020000 020000 020000

020000 020000 020000 020000 020000 020000 020000 020000 020000 020000  
020000 020000 020000 020000 020000 020000 020000 020000 020000 020000  
020000 020000 020000 020000 020000 020000 020000 020000 020000 020000

020

020000 020000 020000 020000 020000 020000 020000 020000 020000 020000  
020000 020000 020000 020000 020000 020000 020000 020000 020000 020000  
020000 020000 020000 020000 020000 020000 020000 020000 020000 020000

020000 020000 020000 020000 020000 020000 020000 020000 020000 020000

020000

020000 020000 020000 020000 020000 020000 020000 020000 020000 020000

020000 020000 020000 020000 020000 020000 020000 020000 020000 020000