

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals

SUBMIT IN TRIPLICATE

1. Type of Well

☒ Oil Well ☐ Gas Well ☐ Other

2. Name of Operator

Conoco, Inc.

3. Address and Telephone No.

10 Desta Drive Ste. 100W, Midland, Tx. 79705-4500 (915) 686-5580/684-6381

4. Location of Well (Footage, Sec., T. R. M. or Survey Description)

1980' FSL & 1980' ^{EL}FWL
Sec 28, T20S, R38E

5. Lease Designation and Serial No.

LC 031695B

6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement Designation

8. Well Name and No.

Warren Unit #8

9. API Well No.

30-025-07844

10. Field and Pool, or Exploratory Area

Warren Drinkard

11. County or Parish, State

Lea, N.M.

12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

- ☐ Notice of Intent
☒ Subsequent Report
☐ Final Abandonment Notice

TYPE OF ACTION

- ☒ Abandonment
☐ Recompletion
☐ Plugging Back
☐ Casing Repair
☐ Altering Casing
☐ Other

- ☐ Change of Plans
☐ New Construction
☐ Non-Routine Fracturing
☐ Water Shut-Off
☐ Conversion to Injection
☐ Dispose Water

Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

10-20-99: MIRU, POOH w/rods & pump, ND wellhead, NU BOP, run packer. SION.

10-21-99: Set packer, test BOP, RIH latch onto packer, release packer, POOH w/packer, pulled tubing. SION.

10-22-99: Finish pulling tubing, tagged packer-RU swivel, sting into packer w/packer picker, SION.

10-25-99: Bled well done, POOH w/86 stands of 2 7/8" tubing, pull jars, packer picker w/packer through wellhead, packer stuck. Release packer picker & pull packer out of wellhead. Installed wellhead & BOP. Running tubing to top of perms. SION.

10-26-99: Open well, picked up tubing, rig up swivel pump, got circulation, cleaned out to 6692', drill out 5' cement & CIBP, run to 6804' & circulate clean, lay down swivel, POOH w/40 jts, SION.

10-27-99: Open up well, POOH w/2 7/8" tubing, NU wellhead & BOP, RU wireline, perforated well @6774-6625' w/1 jsp. SION.

10-28-99: RIH, testing tubing to 6790', set RBP@ 6795', set packer @ 6675', SION.

10-29-99: Bled well, RU BJ-acidize lower Drinkard w/2000 gals gelled HCL & 9000 gals of XL Acid II, & 4500 gals slick 15% HCL s/ball sealers. POOH w/tubing & packer, RIH w/tbg, engaged RBP, couldn't get RBP loose, POOH w/tbg & pkr, RIH w/retrieving tool & tubing, engaged RBP, reset RBP @ 6680', POOH w/40 jts., SION.

10-30-99: Bled well, POOH w/tbg, RIH w/retrieving head, RIH set packer @ 6600', BJ acidized w/4000 gals 15% gelled HCL & 6000 gals of XL acid II. 11-1-99: Opened well-swabbed, released pkr & latched onto RBP, tagged PBTD@6806', POOH. SION.

11-2-99: Cont. POOH, RIH w/SOPMA, 2 3/8" tubing, SN@6756', RIH w/rods, spaced out pump & hung on, loaded tbg, SION.

11-3-99: Unseated pump, hot oiled tbg, seated pump, good pump action. RDMO.

14. I hereby certify that the foregoing is true and correct.

Signed

Title

Ann E. Ritchie
Regulatory Agent

Date

December 17, 1999

(This space for Federal or State office use)

Approved by _____
Conditions of approval if any: _____

Title

Date

BLM(6)

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

IC GWW