

NEW MEXICO OIL CONSERVATION COMMISSION

AUG 22 11 51 AM '67

NO. OF COPIES RECEIVED

DISTRIBUTION

SANTA FE

FILE

U.S.G.S.

LAND OFFICE

OPERATOR

5a. Indicate Type of Lease

State ☒

Fee ☐

5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. Name of Operator

Mobil Oil Corporation

3. Address of Operator

Box 633, Midland, Texas

4. Location of Well

UNIT LETTER **D** **660** FEET FROM THE **North** LINE AND **660** FEET FROM

THE **West** LINE, SECTION **36** TOWNSHIP **20-S** RANGE **38-E** NMPM.

15. Elevation (Show whether DF, RT, GR, etc.)

7. Unit Agreement Name

8. Farm or Lease Name

New Mexico "F" #1

9. Well No.

1

10. Field and Pool, or Wildcat

Terry Blinebry

12. County

Lea

16.

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐

TEMPORARILY ABANDON ☐

PULL OR ALTER CASING ☐

OTHER ☐

PLUG AND ABANDON ☒

CHANGE PLANS ☐

REMEDIAL WORK ☐

COMMENCE DRILLING OPNS. ☐

CASING TEST AND CEMENT JOB ☐

OTHER ☐

ALTERING CASING ☐

PLUG AND ABANDONMENT ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Plugging Procedure:

1. Run 2-3/8" tubing open ended to 4980' (plug back TD) and displace hole to mud laden fluid 9.0 #/gas. or heavier.
2. Pull tubing to 4350' and spot 35 sx neat cement.
3. Pull tubing to 3005' and spot 35 sx neat cement.
4. Place 10' cement plug at surface and install marker.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED

TITLE

Authorized Agent

DATE

August 18, 1967

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY: