

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Nov 22 11 53 AM '66

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease
State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.
<b>B-9445</b>

**SUNDRY NOTICES AND REPORTS ON WELLS**

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator <b>Skelly Oil Company</b>	8. Farm or Lease Name <b>State U</b>
3. Address of Operator <b>P. O. Box 730, Hobbs, New Mexico</b>	9. Well No. <b>1</b>
4. Location of Well UNIT LETTER <b>"A"</b> <b>660</b> FEET FROM THE <b>North</b> LINE AND <b>660</b> FEET FROM THE <b>East</b> LINE, SECTION <b>5</b> TOWNSHIP <b>22-S</b> RANGE <b>35-E</b> NMPM.	10. Field and Pool, or Wildcat <b>San Simon</b>
15. Elevation (Show whether DF, RT, GR, etc.) <b>3623' DF</b>	12. County <b>Lea</b>

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>
OTHER <b>Plug and Abandon</b> <input checked="" type="checkbox"/>	OTHER <input type="checkbox"/>
PLUG AND ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

**STATE "U" WELL NO. 1**

This well is no longer profitable to operate. There are no other commercial zones of oil or gas in this well. We plan to plug and abandon the well in the following manner:

1. Move in and rig up Pulling Unit.
2. Pull rods and tubing.
3. Spot 55 sack cement plug from 3885' to 4144'.
4. Cut and pull 7"OD from approximately 3500'.
5. Spot 25 sack plug on the inside and the outside of the cut off point on the 7"OD casing.
6. Spot 25 sack plug from 3400' to 3500'.
7. Spot 25 sack plug from 1740' to 1840'.
8. Spot 35 sack plug in bottom of 16"OD, casing, which is set at 96'.
9. 10 sack cement cap at surface with 4' X 4" steel marker.
10. All intervals not cemented will be filled with heavy mud laden fluid.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED **(ORIGINAL) H. E. Aub** TITLE **District Superintendent** DATE **November 21, 1966**

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_  
CONDITIONS OF APPROVAL, IF ANY: