

COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. B-8244
7. Unit Agreement Name Jalmar Field Yates Sand Unit
8. Farm or Lease Name
9. Well No. 120
10. Field and Pool, or Wildcat Jalmar
12. County Lea

SUNDRY NOTICES AND REPORTS ON WELLS

DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>
2. Name of Operator Gulf Oil Corporation
3. Address of Operator Box 670, Hobbs, New Mexico 88240
4. Location of Well UNIT LETTER <u>0</u> FEET FROM THE <u>South</u> LINE AND <u>1650</u> FEET FROM THE <u>East</u> LINE, SECTION <u>11</u> TOWNSHIP <u>22-S</u> RANGE <u>35-E</u> N.M.P.M.
15. Elevation (Show whether DF, RT, GR, etc.) 3609' GL

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK	<input type="checkbox"/>
TEMPORARILY ABANDON	<input type="checkbox"/>
PULL OR ALTER CASING	<input type="checkbox"/>
OTHER <u>Plug and Abandon</u>	<input type="checkbox"/>

PLUG AND ABANDON	<input type="checkbox"/>
CHANGE PLANS	<input type="checkbox"/>

REMEDIAL WORK	<input type="checkbox"/>
COMMENCE DRILLING OPNS.	<input type="checkbox"/>
CASING TEST AND CEMENT JOB	<input type="checkbox"/>
OTHER	<input type="checkbox"/>

ALTERING CASING	<input type="checkbox"/>
PLUG AND ABANDONMENT	<input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

4031' TD, 4026' PB.

Pull producing equipment. Run CI BP on tubing and set at 3800'. Displace hole with produced water containing 25 sacks of gel per 100 barrels of water. Spot 35 sacks Class C cement plug on top of BP. Pull tubing. Load hole with mud. Spot 50' cement plug from 50' to surface. Install dry hole marker and clean location.

100' plug inside pipe @ top 50 ft
24 hr. notice

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED K. J. Bruzale

TITLE Area Engineer

DATE March 22, 1973

APPROVED BY _____

TITLE _____

DATE MAR 23 1973

CONDITIONS OF APPROVAL, IF ANY: