

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	
E-2682	
7. Unit Agreement Name	
Jalmar Field Yates Sand Unit	
8. Farm or Lease Name	
9. Well No.	
117	
10. Field and Pool, or Wildcat	
Jalmar	
12. County	
Lea	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE APPLICATION FOR PERMIT (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <input checked="" type="checkbox"/>	2. Name of Operator
	Gulf Oil Corporation
3. Address of Operator	Box 670, Hobbs, New Mexico 88240
4. Location of Well	UNIT LETTER <u>N</u> <u>660</u> FEET FROM THE <u>South</u> LINE AND <u>1980</u> FEET FROM THE <u>West</u> LINE, SECTION <u>12</u> TOWNSHIP <u>22-S</u> RANGE <u>35-E</u> NMPM.
15. Elevation (Show whether DF, RT, GR, etc.)	3606' GL

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
CASING TEST AND CEMENT JOBS <input type="checkbox"/>	
OTHER <input type="checkbox"/>	

Plugged and abandoned.

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

3908' TD, 3900' PB.

Could not pull tubing. Cut and recovered 2-1/16" tubing from 3713', leaving 10' tubing and packer in hole. Ran CI BP and set at 3639'. Loaded hole with gel water. Spotted 5 sack cement plug on top of BP. Spotted 15 sack cement plug from 2001' to 1849', across salt. Spotted 15 sack cement plug from 100' to surface. Installed dry hole marker and cleaned location. Plugged and abandoned June 18, 1974.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>B. Barba</u>	TITLE <u>Area Engineer</u>	DATE <u>June 18, 1974</u>
APPROVED BY <u>John W. Pungson</u>	TITLE <u>Geologist</u>	DATE <u>SEP 18 1974</u>
CONDITIONS OF APPROVAL, IF ANY:		