

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

IL CONSERVATION DIVISION

P. O. BOX 2088

SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. E-8077

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT - I" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER: Water injection well	7. Unit Agreement Name Jalmat Yates Pool Unit
2. Name of Operator J.R. Cone	8. Farm or Lease Name Tract 8
3. Address of Operator Box 10217, Lubbock, TX 79408	9. Well No. 3
4. Location of Well UNIT LETTER F, 1980 FEET FROM THE North LINE AND 1980 FEET FROM THE West LINE, SECTION 25 TOWNSHIP 22-S RANGE 35-E NMPM.	10. Field and Pool, or Wildcat Jalmat (Oil)
15. Elevation (Show whether DF, RT, GR, etc.) 3572Gr;3584 KB (datum)	12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐
PULL OR ALTER CASING ☐
OTHER ☐

PLUG AND ABANDON ☐
CHANGE PLANS ☐

REMEDIAL WORK ☐
COMMENCE DRILLING OPNS. ☐
CASING TEST AND CEMENT JOBS ☐
OTHER ☐

ALTERING CASING ☐
PLUG AND ABANDONMENT ☒

Conversion to water injection
Under administrative order WFX #276

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1503.

Basic well data: TD 3960' KB; PB 3940'. 5 1/2"-14 1/2" csg, cem. @3942' w/1900 sx; cement circulated. Top Yates 3714. Csg. perf'd 3810-3828 (Yates Zone III) w/JSPF. Initial compl. as oil well Dec 23, 1956.

Water injection, Sept. 2.-Oct. 30, 1967.

December 11, 1985-Spot 20 sx cement 3690 to 3520. WOC 4 Hrs. and tag plug @3485 spot 60 feet mud. Pull up hole to 1659 and spot 20 sx cement to 1485. WOC and tag plug @1450. Mixed and pumped mud. Pulled out of hole to 376 and spotted 20 sx cement 376 to 213. WOC 4 hrs. and tagged @210. Mixed 10 sx surface plug and installed marker.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>James R. Cone, Jr.</u>	TITLE <u>Agent</u>	DATE <u>12-19-86</u>
APPROVED BY <u>R. A. Lublin</u>	TITLE <u>OIL & GAS INSPECTOR</u>	DATE <u>APR 13 1988</u>
CONDITIONS OF APPROVAL, IF ANY:		