STATE OF NEW MEXICO ENERGY AND MINERALS DEPARTMENT

	Ī	
DISTRIBUTION		
SANTA FE		
FILE		
U.\$ G.\$.		
LAHD OFFICE		
OPERATOR		

OIL CONSERVATION DIVISION P. O. BOX 2088

Form C-103 .

FILE	SANTA FE, NEW MEXICO 87501	Keased In-1-18
U.\$ 0.\$.		5a. Indicate Type of Lease
LAND OFFICE		State Y F.
OPERATOR		5, State Oil & Gas Lease No.
	Mary .	E-2997
SUNI	DRY NOTICES AND REPORTS ON WELLS	
(I)O NOT USE THIS FORM FOR USE "APPLIC	DRY NOTICES AND REPORTS ON WELLS PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. ATION FOR PERMIT - " IFORM C-101) FOR SUCH PROPOSALS.	
•		7. Unit Agreement Name
WELL SAB SELL	other. Water injection well	one Jalmate Yates Pool
, Name of Operator		8. Form or Lease Hame
J. R. Cone		Tract 10
. Address of Operator		9. Well No.
P.C Box 10217 Lub	bock, Texas , 79408	1
. Location of Well		10. Field and Pool, or Wildcat
UNIT LETTER A	660' FEET FROM THE North LINE AND 660' PEET FROM	Jalmatæ(oil)
UNIT LETTER,,	PEET FROM THE TOT CIT LINE AND OOU FEET FROM	Od I mack (OII)
East	TION 36 TOWNSHIP T22S RANGE R35E NMPM.	
THE LINE, SEC	TION TOWNSHIP 1223 RANGE KODE NMPM.	
mmmmm	15. Elevation (Show whether DF, RT, GR, etc.)	The state of the s
	3535 DF (9' above GL)	12. County
		Lea
Check	Appropriate Box To Indicate Nature of Notice, Report or Oth	ner Data
NOTICE OF	INTERIOR DE LA COMPANION DE LA	REPORT OF:
PERFORM HEMEDIAL WORK	PLUG AND ABANDON REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON	COMMENCE DRILLING DPMS.	PLUG AND ABANDONMENT
PULL OR ALTER CABING	CHANGE PLANS CASING TEST AND CEMENT JOB	TO ABARDUMENT
_	OTHER	\Box
OTHER		
		. •
7. Describe Proposed or Completed work) SEE RULE 1103.	Operations (Clearly state all pertinent details, and give pertinent dates, including	estimated date of starting any proposed =
Basci well Data:	TD 3840' 515" J55 15# csng cemented @ 384	0' w/250 sax in 7 7/8" hole
	9 3/6 H4U 32# csng cemented @	321' cement circulated in
	12 1// noie.	=
	Top of Yates	
	Yates perforsted 3789'-3821' and 3740'-52'	
	Baker tension packer on 2 3/8" tubing set at 32	00 +
	The state of the s	- , , , ,
11-11-85		
	Pulled 2 3/8 tubbing and safty collar from pack	or Pushed packer to 2005
	and spot 30 sacks cement 3801 to 3441. Tag plus	er, rushed backer to 3835
	Circulated hole with mud. Spot 20 sack cement	y w ანის. 1660 to 1400
	Perferate 321' and displace 50 sacks cement to	1000 T.O [49]).
	to 1000#. Set 5 sack surface and install market	270' pressure tes t
·	22 2000%. See 3 Sack Surrace and Instart market	r.
		2
. I hereby certify that the information	on above is true and complete to the best of my knowledge and belief.	
1	1)	
Same of K	Agent Agent	0_12_06
· · · · · · · · · · · · · · · · · · ·	Title Tigette	OATE 9-12-86
	10 0	
1/ 12 1	OIL & GAS INSPECTOR	4848 1 3 1988 - 1
Moves or _ Na		· · · · · · · · · · · · · · · · · · ·