

Submit 3 Copies To Appropriate District Office  
District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Rd., Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-103  
Revised March 25, 1999

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		WELL API NO. 30-025-08731
1. Type of Well Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other <input type="checkbox"/>		5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
2. Name of Operator Chevron USA, Inc.		6. State Oil & Gas Lease No.
3. Address of Operator 15 Smith Rd. Midland, Tx 79705		7. Lease Name or Unit Agreement Name Arrowhead Grayburg Unit
4. Well Location Unit Letter B : 660 feet from the North line and 1980 feet from the East line Section 01 Township 22-S Range 36-E NMPM County Lea		8. Well No. 147
10. Elevation (Show whether DR, RKB, RT, GR, etc.)		9. Field Name or Well Name Arrowhead - Grayburg

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	MULTIPLE COMPLETION <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER: <input type="checkbox"/>
OTHER: <input type="checkbox"/>			

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.

1. Tag CIBP @ 3640' spot 25sx plug fr/3640' to 3504' (T/AGU) Tag @ 3281'
2. Displace hole w/MLF 9.5# Brine w/25# Gel p/BBL
3. Spot 25sx plug fr/2560' to 2460' (B-salt)
4. Perf 4 holes @ 1265' sqz w/75sx fr/1265' to 1165'(T-salt) Tag @ 1051'
5. Perf 4 holes @ 343' sqz w/75sx fr/343' to surf( 10 3/4" shoe) Tag @ surf
6. Install dry hole marker 9-3-02

Approved as to plugging of the Well Bore.  
Liability under bond is retained until  
surface restoration is completed.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Poly Alvalos TITLE SUNSET / MANAGER DATE 9/3/02  
Type or print name Poly ABALOS Telephone No. (915) 520-8756  
(This space for State use)

APPROVED BY GARY W. WINK TITLE GWC FIELD REPRESENTATIVE II/STAFF MANAGER DATE FEB 13 2003  
Conditions of approval, if any: GWW