

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department
OIL CONSERVATION DIVISION

Form C-103
Revised 1-1-89

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

DISTRICT I

P.O. Box 1980, Hobbs, NM 88240

DISTRICT II

P.O. Drawer Dd, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, Nm 87410

API NO. (assigned by OCD on New Wells) 30-025-08738	
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>	
6. State Oil & Gas Lease No. N/A	
7. Lease Name or Unit Agreement Name ARROWHEAD GRAYBURG UNIT	
8. Well No. 151	
9. Pool name or Wildcat ARROWHEAD/GB	

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL <input type="checkbox"/> GAS <input type="checkbox"/> WELL <input checked="" type="checkbox"/> WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	
2. Name of Operator CHEVRON U.S.A. INC.	
3. Address of Operator P.O. BOX 1150 MIDLAND, TX 79702 ATTN: NITA RICE	
4. Well Location Unit Letter B : 660 Feet From The NORTH Line and 1980 Feet From The EAST Line Section 2 Township 22 SOUTH Range 36E NMPM LEA County	
10. Elevation(Show whether DF, RKB, RT, GR, etc.) 3557' GL	

11

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTER CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABAN. ☐
CASING TEST AND CMT JOB ☐
OTHER: **DEEPEN, LOG, ACDZ, SQZ OFF WTR** ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including
estimated date of starting any proposed work) SEE RULE 1103.

WORK STARTED 12/15/93. MIRU PU, ND WH, NU BOP. SET RBP @3700'. SWAB.
POOH W/RBP & TBG. DRILL TO 3965'. LOG PULSED NEUTRON/GR/CCL.
ACDZ W/2520 GALS 15% NEFE HCL. FLUSH. SWAB.
DUMP 11 SX SD IN OPEN HOLE FROM 3965'-3811'. SET CICR @3648'.
MIX & PUMP 250 SX 2% CAL CHLORIDE NITRIFIED, MIX & PUMP 50 SX CMT W/O NITROGEN.
D/O CMT TO 3648', CIRC HOLE CLEAN. DRILL THRU CICR & 3 FT OF CMT.
DRILL CMT F/3650'-3810'. SWAB. D/O TO TD 3965'. CIRC FRAC SAND F/3839'-3854'.
GIH W/PROD TBG. ND BOP, NU WH. RD PU, TURN OVER TO PRODUCTION 1/10/94.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Wendi Kingston TITLE **TECH. ASSISTANT** DATE: **03/29/94**
TYPE OR PRINT NAME **WENDI KINGSTON** TELEPHONE NO. (915)687-7436

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

ORIGINAL SIGNED BY JERRY SEXTON
TITLE **DISTRICT I SUPERVISOR** DATE

MAR 31 1994