

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease
State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.
B-1534

## SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator CONOCO INC.	8. Farm or Lease Name State J-2
3. Address of Operator P. O. Box 460, Hobbs, N.M. 88240	9. Well No. 2
4. Location of Well UNIT LETTER <u>I</u> , <u>1980</u> FEET FROM THE <u>South</u> LINE AND <u>660</u> FEET FROM THE <u>East</u> LINE, SECTION <u>2</u> TOWNSHIP <u>22S</u> RANGE <u>36E</u> N.M.P.M.	10. Field and Pool, or Wildcat Arrowhead Grayburg
11. Elevation (Show whether DF, RT, GR, etc.)	12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	acidize <input checked="" type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1703.

- ① MIRU on 1-15-86, POOH w/tbg & rods. Tag top of liner @ 3700' (liner 3700'-3840')
- ② Could not get into liner. Mill 5' in liner. Did not make any progress.
- ③ Set pkr @ 3670' & acidized w/ 15 1/2 bbls 15% HCL. POOH w/pkr. tbg stuck in hole.
- ④ Catch fish @ 3737' and POOH.
- ⑤ Set pkr @ 3690' & acidized w/ 30 bbls 15% HCL; flushed w/ 30 bbls TFW
- ⑥ w/H w/tbg & rods. HWO & rig down on 2-14-86
- ⑦ Test pumped 28 BO, 157 BW, 8 MCF on 2-25-86

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED [Signature] TITLE Administrative Supervisor DATE 2-26-86

ORIGINAL SIGNED BY JERRY SEXTON  
DISTRICT I SUPERVISOR

CONDITIONS OF APPROVAL, IF ANY:

TITLE DATE

MAR 3 - 1986

NMOC-D-Hobbs(3)File

RECEIVED  
FEB 28 1986  
HOBBS OFFICE